


# **Measurement Range and Accuracy** (Specified for 23°C±5°C, <80% RH)

| Range    | Resolution | Accuracy         | Notes   |
|----------|------------|------------------|---|
| D 200mV  | 100µV      | ±0.5%rdg.±4dgt.  | Input resistance: >100MΩ                      |
| C 20V    | 1mV        | ±0.7%rdg.±4dgt.  | // 10MΩ (approx)                              |
| V 200V   | 0.1V       | //               | //  |
| V 1000V  | 1V         | ±1.0%rdg.±4dgt.  | //  |
| A 2V     | 1mV        | ±1.0%rdg.±8dgt.  | Input resistance: 10MΩ<br>(approx) (40~500Hz) |
| C 20V    | 0.1V       | //               | //  |
| V 600V   | 1V         | ±1.2%rdg.±8dgt.  | //  |
| D 200mA  | 100µA      | ±1.5%rdg.±4dgt.  | approx. 1Ω (not including fuse resistance)    |
| C 10A    | 10mA       | ±1.7%rdg.±4dgt.  | > approx. 15mΩ                                |
| A 200mA  | 100µA      | ±2.0%rdg.±8dgt.  | approx. 1Ω 40Hz~500Hz                         |
| A 10A    | 10mA       | ±2.2%rdg.±8dgt.  | > approx. 15mΩ                                |
| O 200Ω   | 0.1Ω       | ±0.8rdg.±5dgt.   | Open terminal voltage:<br>1.5V±0.2V           |
| H 2kΩ    | 1Ω         | //               | 0.65V±0.065V //                               |
| M 20kΩ   | 10Ω        | //               | //  |
| S 200kΩ  | 100Ω       | ±1.8%rdg.±10dgt. | //  |
| S 2000kΩ | 1kΩ        | ±1.0%rdg.±10dgt. | Open terminal voltage: <0.4V                  |
| L 20kΩ   | 1Ω         | //               | //  |
| P 200kΩ  | 10Ω        | //               | //  |
| Ω 2000kΩ | 1kΩ        | ±2.0%rdg.±10dgt. | //  |



# English

## **WARNING**

This instrument is designed to prevent accidental shock to the operator when properly used. However, no engineering design can render safe an instrument which is used carelessly. Therefore, this manual must be read carefully and completely before making any measurement. Failure to follow directions can result in a serious or fatal accident.

## 1. Instrument Specifications

**Display:** 3 1/2-digit LCD, maximum reading of '1999', autopolarity, unit symbols.

**Ranging:** Automatic (Manual for current ranges.)

**Overrange Indicator:** '1' in MSD column blinks (except in DC 1000V, AC 600V and AC/DC 10A range.) Beeper sounds (except in DC 1000V, AC 600V, AC/DC 10A, and Ohms range.)

**Battery Low Indicator:** **BATT** mark lights.

**Sampling Rate:** 2 per second.

**Power Source:** Two size AA (SUM-3) batteries; Life: 300 hours continuous use (approx)

**Environmental Conditions (Operating):** 0~40°C, <80% RH. (No condensation)

(Storage): -20~60°C, <70% RH (No condensation)

**Power Consumption:** 5mw (typical)

**Temperature Coefficient:**  $\pm(400\text{ppm} + 0.3\text{dgt})/^{\circ}\text{C}$  (0~30°C)  
 $\pm(400\text{ppm} + 2\text{dgt})/^{\circ}\text{C}$  (30~40°C)

**Maximum Overload Limits :** Volts; DC 1100V, AC 750V (1 min.)  
 $\Omega$  & mA; AC 250V (0.5A non-arcing fuse)  
10A range; AC/DC 12A (1 min.)

**Dielectric Strength:** AC 3kV/1 min (between input terminals and case).

**Dimensions/Weight:** 160H×85W×29D (mm)/250g (approx)

**Accessories Furnished:** Test leads, 0.5A non-arcing fuse

**Optional Accessories:** 9145 Carrying Case, 9014 High-Voltage Test Probe

## 2. Precautionary Notes

- Always check to make sure that the function switch setting and test lead connection is correct before making a measurement.
- The **BATT** mark appearing in the display indicates that the batteries are worn-out. Replace the batteries with new ones.
- Always turn the power switch OFF when not using the instrument.
- Do not store the instrument in a high temperature, high humidity location, and avoid areas where condensation is likely to occur.
- Condition of the internal fuse is checked in the Ohms range with the test leads plugged into the  $\Omega$  • mA and -COM terminals. When shorting the test leads together, a blown fuse is indicated by the display failing to "zero", and indicating that the reading is NG (no good). When this is the

case, replace the fuse.

### 3. Voltage Measurements

**⚠ WARNING:** Maximum allowable input is DC 1000V, or AC 600V.

- ① Plug the red test lead into the V terminal, and the black test lead into the —COM terminal.
- ② Set the function switch to V. (The **AUTO** mark will appear in the display.)
- ③ For DC V measurements, press the AC/DC key to erase the AC mark from the display. (There is no DC mark.) For AC V measurements, press the AC/DC key to light the AC mark in the display.
- ④ Connect the test leads to the circuit under test and read the value from the display.

**NOTE:** In the DC 200mV range (autoranging), since input resistance is a high value ( $>100M\Omega$ ), noise will cause the display to show a reading even though there is no measurement input. In this case, short the test lead tips together. If the display will zero, the measure will be accurate.

**NOTE:** When taking voltage measurements where spikes and other distortion are present in the waveform (e.g., horizontal output from a TV set, etc.), use positive (+) polarity readings. Negative (—) polarity readings will be grossly erroneous.

**NOTE:** There is no 200mV range with AC V.

### 4. Ohms ( $\Omega$ and LP $\Omega$ ) Measurements

**NOTE:** When the test lead tips are shorted together in the lowest range, 2 to 3 counts will typically be indicated in the display. (This is not a defect.)

**NOTE:** There is no 200 $\Omega$  range with the LP $\Omega$  function.

- ① Plug the red test lead into the  $\Omega \cdot mA$  terminal, and the black test lead into the —COM terminal.
- ② Set the function switch to  $\Omega$ . (The **AUTO** mark will appear in the display.)
- ③ For  $\Omega$  measurements, press the LP $\Omega$ / $\Omega$  key and erase the **LP $\Omega$**  mark from the display. For LP $\Omega$  measurements, press the LP $\Omega$ / $\Omega$  key to light the **LP $\Omega$**  mark.
- ④ Connect the test leads to the circuit or component under test and read the value from the display.

**NOTE:** Both  $\Omega$  and LP $\Omega$  functions are autoranging.

**NOTE:** The Ohms function includes both  $\Omega$  and LP $\Omega$ . In the LP $\Omega$  function, open terminal and full-scale voltages are less than those for the standard

$\Omega$  function.  $LP\Omega$  should be used for in-circuit measurements in microcircuits containing semiconductors that should have less than 0.5V applied to them.

### **5. AC and DC Current Measurements) (Manual ranging)**

① With the meter in the AC/DC 200mA range, plug the red-test lead into the  $\Omega \cdot mA$  terminal, and the black test lead into the  $-COM$  terminal. If the meter is in the AC/DC 10A range, plug the red test lead into the 10A terminal, and the black lead into the  $-COM$  terminal.

② Set the function switch to 200mA or 10A. (The **AUTO** mark will be extinguished.)

③ For DC current measurements, press the AC/DC key to erase the AC mark from the display.

For AC current measurements, press the AC/DC key to light the AC mark.

④ Connect the test leads to the circuit under test and read the value from the display.

\* Measurements in the 10A range should be completed in under 3 minutes due to heat produced by such high current values.

### **6. Continuity Test**

① Plug the red test lead into the  $\Omega \cdot mA$  terminal, and the black lead into the  $-COM$  terminal.

② Set the function switch to the  $\Omega$  position.

③ Continuity is indicated when the display reads 19 counts or less (in the lowest range), and the beeper sounds.

**NOTE:** Either  $\Omega$  or  $LP\Omega$  can be used for the continuity test.

### **7. Battery and Fuse Replacement**

Both batteries and the spare fuse are located inside the battery holder. When replacing the batteries, make sure that the pole polarity markings are observed.