HIOKI

1

.

3232

INSTRUCTION MANUAL

DIGITAL Hi tester

HIOKI E.E. CORPORATION

3232-6G-F

WARNING

Δ in high power circuit area (distribution transformer and bus
BAR)
BEFORE ATTEMPTING ANY MEASUREMETNT, DOUBLE CHECK THAT THE
RANGE SWITCH IS AT THE CORRECT POSITION.
IF THE RANGE IS INCORRECTLY SET, A DANGEROUS ARC OF EXPLOSION
WOULD OCCUR.

Contents

1.			
2.		ations ·····	
3.	Operati	ng instructions	5
3	-∣. Cau	tions ·····	5
3	-2. Nam	nes of sections and functions	6
		Front panel	
		Functions	
	3-2-3.	Rear panel	9
3	-3. Mea	suring method	9
	3-3-1.	Direct current voltage measurement	9
		Alternating current voltage measurement ······	
	3-3-3.	Resistance measurement	11
		Direct and alternating current measurement	
		Frequency measurement	
	3-3-6.	Diode test, continuiry test	14
4.	Data ou	tput	15
5.	Handle	operation	•••••• 20
6.		g battery	
7.		g fuse	
8.	Applicat	ons ·····	······ 21

I. Outline

The 3232 digital hi-tester is a digital multimeter for frequency, diode test, and continuity test functions in addition to direct current voltage, altenating current voltage, resistance, direct current, and alternating current measurement functions. It has output data and facilitates Zero adjustment at full count.

2. Specifications

Measuring method: Double intergral method

- **Display:** 3 1/2 digits LED, character height : 18mm Max. 3199 with unit symbols (decimal point, mV, V, Ω , $k\Omega$, $M\Omega$, μA , mA, A, Hz, kHz, AC $\rightarrow -$ [LP Ω], [ADJ], [B], AUTO, HOLD, ""
- Range change: Auto & manual (manual only for current and frequency)
- Input over display: "OF" or "=OF" (excluding DC1000V, AC750V, DC/ AC10A)

Buzzer alam (excluding DC1000V, AC750V, DC./AC10A, Ω) Polarity display: Only "-" is displayed automatically Battery Low: \blacksquare mark lights up (at 4.2 v and less, ± 0.1 V)

Sample rate: 2.5times/second

Operating temperature and humidity: 0° C to 40° C at less than 80° humidity

Storage temperature and humidity: $-\!\!-\!\!-\!\!20^\circ\!\!C$ to $60^\circ\!\!C$, at less then 70% humidity

Temperature property: (400 ppm + 0.3 dgt) 10 °C.

AUTO POWER OFF: Power turns off 60 minuters after the last setting. Turn to off to start measuremet.

Four size AA Power source (SUM-3)×4(250|hours continuous use at DCV) Power consumption: 15mW TYP, (DCV) 18mW TYP, (ACV) Withstand voltage: AC 3 kV (one minute) Terminal-case Dimensions and weight: 160(H)×85(W)×33(D)mm 800g (Approx) Accessory: 9170 test leads; battery, SUM3×4; Spare fuse 0.5A/250V (dia. 6.4×30) nonarcing type. Optional Accessory: 9014 high voltage probe

Maximum overload input:

V/Hz terminal: I I00VDC or DC \pm AC peak one minute

 $\Omega/u mA/$ \rightarrow + terminal: 250V AC Max. one minute, protected by fuse

10A terminal: 12A DC/AC one minute

* Frequency measurement is separately specified.

- 2 -

Measuring range (23°C \pm 5°C, 80%RH or less no condensation)

After zero adjustment

Function	Range	Accuracy	Note
	300mV	$\pm (0.35\%$ rdg $+ 2$ dgt)	>100MΩ
	3V	n	$11M\Omega$ (Approx)
DCV	$\sim 30V$	п.	10MΩ (Approx)
	300V	+ (0.5%rdg + 2dgt)	<i>n</i>
	1000 V	$\pm (0.6\%$ rdg ± 2 dgt)	· · · · · · · · · · · · · · · · · · ·
	3V	$\pm (1.0\%$ rdg ± 4 dgt)	$11M\Omega$ (Approx)
	30V	,,	10MΩ (Approx) 40
ACV	300 V	· <i>n</i>	″ ^J ~500Hz
	750V	<i>p</i>	n n
	300 Ω	$\pm (0.4\% rdg + 2dgt)$	Open terminal voltage <1.5V (Ap-
	3kΩ	·	prox)
	$30k\Omega$	·	
Ω	$300 k\Omega$	<i>11</i>	$0.65V \pm 0.2V$
	3000kΩ	\pm (1.0%rdg+2dgt)	
	$30M\Omega$	+ $(2.0\%rdg + 2dgt)$	· · · · · · · · · · · · · · · · · · ·
	3kΩ	$\pm (0.5\%$ rdg ± 4 dgt)	<u>)</u>
	$30k\Omega$	п	· · · · · · · · · · · · · · · · · · ·
L. ΡΩ	$300 k\Omega$	"	<0.45V
	$3000 k\Omega$	\pm (1.0%rdg+4dgt)	
	30MΩ	\pm (2.0%rdg+4dgt)	
	30mA	\pm (1.0%rdg+2dgt)	100 (Approx)
DCA	300 mA	11	1Ω (Approx)
1	10 A	\pm (1.2%rdg+2dgt)	<15m0
	30mA	+ (1.2%rdg+4dgt)	(Approx)10Ω \
ACA	300mA	"	1Ω 40~500Hz
	10A	\pm (1.5%rdg+4dgt)	<15mΩ
	300Hz	$\pm (0.15\%$ rdg $+ 2$ dgt)	$\approx 10 \sec c$ > approx 1-M Ω
Hz	3kHz	\pm (0.1%rdg 1dgt)	lsec AT lkHz
H12	30kHz	"	0.1sec {30Hz~
	300 kHz	<i>n</i>	0.1sec 320kHz)
Conti-	Threshole	Hebel: less than 2kG or less	Open terminal voltage
nuity	Responce	time 100msec ⁺ approx .	<about 1.5v<="" td=""></about>
Remain		one digit.	

≫Gate time

Frequency measurement Maximum input sensitivity

	LOWE R Sine wave	LIMIT Rectangular wave	UPPER	1,1MIT	Overicad voltage one minute
30H z - 320kHz	500mVrms	600mVp-p	5 O V	AC	300V DC+ACpeak

3. Operating instructions

A WARNING

This instrument is desingned to prevent accidental shock to the operator when properly used. However, no engineering disign can render safe an instrument which is used carelessly. Therefore, this manual must be read carefully and completely before making any measurement. Failure to follow directions can result in a serious or fatal accident.

3-1. Names of sections and functions

Precautionary Notes

- •The BATT mark appearing in the display indicates that the batteries are worn-out. Replace the batteries with new ones,
- Always turn the power switch OFF when not using the instrument.
- Always check to make sure that the function switch setting is correct, and that the test leads are plugged in to the proper terminals before making a measurement.

In order to protect circuitry, a fuse is provided for V \cdot Ω \cdot Hz \cdot

- \Rightarrow \land mA terminals. No measurement is possible at these terminals if the fuse is burned. If open-circuit is indicated (∞ ohms when touching both leads together in \Rightarrow \land function), replace the fuse.
- Do not store the instrument in a high temperature, high humidity location, and avoid areas where condensation is likely to occur.

-5-



3-2-2. Functions

(I)Autorange

In autorange the optimum range is selected automatically without setting the range key.

Set the range manually when making measurements close to full scale since the range – up moves the range higher between $2800 \approx 2200$. The manual dama measure the means the range of 200.

3200. The range – down moves the range lower at 269.

①Autorange is actuated (AUTO mark lamp glows) in the following cases.

In V or Ω function

•AC, LP Ω /DC, Ω key is depressed

When the range key is kept depressed for several seconds.

②Manual operation (AUTO mark lamp turns off)

•When range key is turned on.

•When the function key is turned to Hz, $\nleftrightarrow 1$, 300μ A, 30mA, 300mA, |0A.

•When 0ADJ key is depressed and <u>ADJ</u> mark lamp glows (2) 0ADJ (zero adjestment)

When the OADJ kay is depressed, <u>ADJ</u> mark lamp will light up and data turns to zero. If the value is X_0 when the OADJ key is depressed, display turns to $X - X_0$ for the input of a next value X. It is useful for offsetting the resistance of test leads or measuring differences. However, it compensates up to +3199 only and excessive count is shown by "OF" or "--OF". This applies when input is excessive for the range (e. g. input of ±3.2V or over in DC 3V range).

ADJ condition may be released by pressing the OADJ key or by changing the function key to $AC \cdot LP\Omega \cdot Hz/DC \cdot \Omega \cdot$ $\Rightarrow 0$ or by turning off the power switch.

- 7 ---

- Note: <u>ADJ</u> mark may be displayed when the key switch is depressed or when measurement result is shown.
- , Note: When <u>ADJ</u> mark is turned on, the range is fixed even in the autorange and the range cannot be changed until autorange is released.
- Note: While display is blank (Hz measurement or when function is being changed), zero adjestment cannot be made.
- Note: Zero adjestment cannot be made with 🏞 🕨 function key.
- Note: When <u>ADJ</u> conditon is released by the 0ADJ key, the conditon prior to zero adjectment will be reinstated.

(3)Hold function

Each time the HOLD key is depressed, the HOLD mark glows and all the data is hold, with the exception of \blacksquare mark. While data is hold no switch functions except for the HOLD key (Unless the display lamp is on.)

The HOLD condition is released by pressing the HOLD key or by turning off the power switch.

Note: Data hold does not operate in 🍽 🕽 functions.

Note: The HOLD condition is not released by changing function. (4)Range control function

Setting from autorange (V, Ω function) to manual range must be done each time the range key is depressed. Each time the range key is depressed the autorange is fixed and each time the key switch is depressed the range goes up one range higher. After the highest - range, the dislpay returns to the lowest range, and this process is repeated.

To return to autorange, depress the range key for several seconds, change function switch to AC \cdot LP Ω \cdot Hz/DC $\cdot \Omega \cdot \not\rightarrow \not$ key, or turn off the power switch.

(5)Overflow

If reading exceeds 3200 in each function range, "OF" on \pm side and " \pm OF" on \pm side are displayed. Decimal point, unit and symbol of that range are displayed(so is <u>ADJ</u> mark lamp.).

(6)Buzzer

- **•** If reading exceeds 3200 in each function range, the buzzer sounds intermittently, except for Ω , $\square P\Omega$, $\Rightarrow \emptyset$ functions.
- ●The buzzer also sounds continuosly at less than the threshold level in ➡ ♪ function.

3-2-3. Names and functions on rear panel Note: See paragraph 4 for data output.

AC Adapter jack

Connecter for data output Fuse holder AC adapter jack

Connect the AC adapter (DC 6V) to this terminal. The center pin is negative. $(\bigcirc -\bigcirc - \bigcirc)$

3-3. Measuring method

Place batteries in the case, after referring to instructions for replacing battery (6).

In AC adapter operation, AC adapter cord to the AC adapter jack, and insert the adapter plug into AC outlet. Turn on the power switch.

3-3-1. Direct current voltage measurement

∆WARNING:

Maximum allowable input is DC 1000V

--8---

 \bigcirc Plug the red test lead into the V terminal, and the black test lead into the -COM terminal.

②Set the range switch to V.

- ③Press the AC LP Ω Hz/DC Ω \Rightarrow \Rightarrow key to obtain the appropriate current mode for the measurement.
- (4)Connect the test leads to the circuit under test and read the value from the display.
- (5)For manual operations, press the RANGE key to make the AUTO mark disappear from the display.
- OFollow this by pressing the **RANGE** key repeatedly until the proper range is obtained.
- OShort the test lead tips together and press the **O ADJ**, key to make the <u>ADJ</u> mark appear in the display. Take the measurement and read the valur from the display.
 - Note: In the DC 300mV range, since input resistance is a high value (> $100M\Omega$), noise will cause the display to show a reading even though there is no measurement input. In this case, shout the test lead tips together and press the **0** ADJ, key to make the <u>ADJ</u> mark appear in the display. The effectively sets the meter to the zero point.
 - Note: When taking voltage measurements where spikes and other distortion are present in the waveform (e. g., horizontal output from a TV set, etc.), use positive (+) polarity readings. Negative (-) polarity readings will be grossly erroneous.

3-3-2. Alternating current voltage measurement

∆WARNING:

Maximum allowable input is AC/750V.

DPlug the red test lead into the V terminal, and the black test lead into the --COM terminal.

②Set the range switch to V.

③Turn AC • LPΩ • Hz/DC • Ω • ➡ ▷ switch to AC. (AC mark glows)
 ④Connect the test leads to the circuit under test and read the value from the display.

⑤For manual operations, press the **RANGE** key to make the **AUTO** mark disappear from the display.

•Follow this by pressing the RANGE key repeatedly until the proper range is obtained.

3-3-3. Resistance measurement (Ω)

 \bigcirc Plug the red test lead into the Ω terminal, and the black test lead into the -COM terminal.

②Set the range switch to Ω .

③Press the AC \cdot LP $\Omega \cdot$ Hz/DC $\cdot \Omega \cdot \not \rightarrow$ key to obtain the appropriate current mode for the measurement.

- ④Connect the test leads to the circuit or component under test and read the value from the display.
- (5)To place the instrument in the manual mode, press the **RANGE** key to make the **AUTO** mark go out of the display.
- Follow this by pressing the RANGE key repeatedly until the proper range is obtained.
- Short the test lead tips together and press the 0 ADJ. key to make

the <u>ADJ</u> make appear in the display. Take the measurement and read the value from the display.

Note) In high resistance measurement, apply shielding or use shield-



$LP\Omega$ (low power ohm)

Many diodes and transistors are used in electronic circuits. When measuring resistance in these circuits, parts must usually be removed from the circuits, since diodes and transistors function when voltage exceeding a certain value is applied. In LP Ω , however, applied voltage is kept low to permit in-circuit measurement.

3-3-4. Direct and alternating current measurement

AWARNING:

Maximaum allowable input 320mA.

 \bigcirc Plug the red test lead into μ A • mA terminal, and the black test lead into the -COM terminal.

②Set the function switch to either 30mA or 300mA range.

③Press the AC/DC key to obtain the appropriate current mode for the measurement. ③Short the test lead tips together and press the **0** ADJ, key to make the ADJ mark appear in the display.

(5)Connect the test leads to the circuit under test and read the value from the display.

10A range

△WARNING:

Maximum allowable input is 10A, and there is no circuit protection in the 10A range. Do not apply voltage to the terminals in this range.

(6)For measurements in the 10A range, plug the red test lead into the 10A terminal.

②Set range to 10A; take the measurement and read the value from the display. (less than 3 min. measurement)

3-3-5. Frequency measurement

Measurement range is 30Hz to 320kHz. Confirm input level before making measurement.

 \bigcirc Connect the red lead to Hz terminal and black lead to -COM.

②Set the function switch to Hz and AC • LPΩ • Hz/DC • Ω • ightarrow
ightarrow switch to Hz side.

③Select frequency range by pressing the range key (manual).

Connect the test leads to object to be measured and read the display.

Note: In frequency measurement, measurement time varies due to gate time. In low frequency, two or more samplings are required.

$3 \pm 3 \pm 6$. Diode test, continuity test

- DPlug the red test lead into the \rightarrow , β , μ A, mA terminal, and the black lead into the -COM terminal.
- x° ②Set the function switch to ↔ ▷. Turn AC LPΩ Hz/DC Ω ↔ ▷ switch to ↔ ▷. Reading before measurement is 1200 to 1800.
- (3)When testing a diode, the \rightarrow , β , μ A, mA terminal will be the + side, and the -COM terminal will be the -side. The anode lead of the diode should be connected to the +side, and the cathode lead connected to the -side in order to get a forward bias reading.(Note that this voltage reading is a rough figure only.) Connecting the diode to the meter backwards produces a meter reading of battery voltage, and this can be used to indicate the good/no good condition of the diode.
- When tesing for continuity, the audible tone will sound, and themark will appear in the display to indicate continuity.

Disregard the display reading.

(The buzzer sounds at less than $2k\Omega$.)

4.Data output

Data is output through the BCD data terminal (A, B, C, D), synchronized with the BCD timing signal (T). Units and function codes are also output. However, 30mA and 10A range signals are output separately. A power source terminals (V, G) are provided. Timing chart is shown in Fig. 2 (negative logic: Active Low)



1.2 ... 10

Confirm data while timing signal is in L (=0).
(1) Output interval: Once each 0.4 second
(2) Output terminal

										n
1	2	3	4	5	6	7	8	9	10	
G	۷	Ν	R 2	R,	Т	D	C	8	Α	
Rı	: 30 r	nA ra	ange	F	2 :	10A r	ange	!	r	Į <u>1</u>
Ν	:No	-conr	nectio	n						
(3)	Outp	ut cir	cuit							Fig. 3
	3232 50 	ка ~~	I OKD		ο ν Ο ου Ο - G	Fig V a				ied externally.

-15-

Note: GND of the output terminal is connected to GND of batterie.

in the body. GND of batteris in the body is 1.5V relative to COM terminal. Therefore, make sure that circuit to be measured and the adapter are insulated.

(4) Data format 👘

2

BCD data is output consecutively from block \bigcirc to block \bigcirc as shown in Fig.2. They are at H level until the next output. In the following description, A is the lowest bit (2°) and D the highest bit (2³).

①The first digit (10°) of display is output in BCD parallel.
②The second digit (10¹) of display is output in BCD parallel.
③The third digit (10²) of display is output in BCD parallel.

Data is shown in Table 1.

Data	A	В	С	D
0	. 1	1	1	1
t	0	1	1	1
2	1	0	1	1
3	0	0	1	1
4	1	1	0	1
5	0	1	0	۱
6	1	0	0	1
7	0	0	0	<u></u> 1
8	1	1	1	0
9	0	1	1	0



(a) The fourth digit (10^3) of display is shown in Table 2.



Table 2

Note: Zero suppressor is shownin Table 3.



Table 3

Note: Overflow is shown in Table 4 and 5.

In case of (OF)

Block	A	B	C	D
1	1	1	1	1
2	1	1	1	1
© 3 4	1	0	1	1
(4)	0	0	1	1

Table 4

-16-

In case of (-OF)

Brock	A	В	С	D
1	1	1	1	1
2	1	1	1	1
3	1	0	1	1
4	0	0	1	0

Table 5

SPositions of decimal points are output in BCD as shown in Table

6. P_1 , P_2 , P_3 are decimal	positions shown in Fig.5.
--------------------------------------	---------------------------

None 1 1 1 1 #. P_1 0 1 1 1 #.	#. ↑	#. ↑
$\begin{array}{ c c c c c c } P_2 & 1 & 0 & 1 & 1 \\ P_3 & 0 & 0 & 1 & 1 \\ \hline \end{array} \begin{array}{ c c c c } P_3 & 0 & 0 & 1 & fig. \end{array}$	'Р₂ 5	Р

#

Table 6

Note: In case of overflow, the point in the range is output.

Units	А	В	C	D
None	1	1	1	1
mV	0	1	1	1
V	1	0	1	1
mA	0	0	1	1
Ω	1	1	0	1
kΩ	0	1	0	1
MΩ	1	0	0	1
Hz	0	0	0	1
kHz	1	1	1	0
		Table 7		

⑦Function codes are output in BCD. Output codes are shown in

⊺able 8.	Func.	A	В	С
	DCV	1	1	1
	ACV	0	1	1
	DCA	1	0	1
	ΑĊΛ	0	0	1
	Ω	1	1	0
	H2	0	1	0
	LPΩ	1	0	0
	- ≱ ♪	0	0	0
		Table 8		

Note: D (2^3) is 0 in 10A range and is 1 in other functions. *Signal in 30mA, 10A range are shown in Table 9.

output	30mA	10A
30mA	0	1
10A	1	0
	Table 9	

- Note: It is I in other than 30mA, IOA range.
- Note: Data in 30mA, 10A range is equivalent to data output in 300mA range. Thus when the signal of 30mA, 10A is output, data needs correction. For instance, 20mA measured in 30mA range will show data 200.0mA which require moving the decimal point. In 10A range, mA must be changed to A.
- Note: Data output while range is being changed in autorange measurement should be ignored.
- Note: In frequency measurement, data is output repeatedly every 0.4 second when gate time is long (in 300Hz and 3kHz range)

- but in 30kHz and 300kHz range, data is output only every 0.4 seconds due to short gate time.
- Note: Sampling time and data output are not synchronized.

5. How to operate the handle

The handle is used as a stand. Pull both ends of the handle, turn it and push it back.



6. Replacing batteries

(1) Remove the battery cover.

(2) Replace batteries, observing correct polarities.

7. Replacing fuse

A fuse is provided on the side of the rear panel. Push the upper side of the fuse holder gently with a finger, pull the fuse out and replace it.

-20-

8. Applications

As described in 4, data is output to BCD code with timing signal. An interface circuit is required to connect external circuits to the data output. An example of parallel interface circuit is shown in Fig. 6. TC4022BP is an octal counter/divider and TC4042BP is a QUAD "d" latch. Process $10^{\circ} - 10^{\circ}$ digits referring to the BCD output of Table 1 and 10° digit, decimal point, unit, and function referring to each code table of the BCD output.

Note) This interface circuit is not necessarily usable for all external circuits. Interface circuit must be determined after carefully studying data input from external circuits.

-21-



.

Fig. 6