

Instruction Manual

TM6101 Measuring Library



Contents

Chapter 1 Overview	5
Chapter 2 Using the Measuring Library	5
2.1 Installing the Library	
2.2 Using the Library	5
Chapter 3 Controlling the TM6101	6
3.1 Overall Process	
3.2 Opening the Instrument	7
3.3 Closing the Instrument	7
3.4 Setting Measurement Conditions	8
Normal Measurement Mode Settings	8
AC Measurement Mode Settings	9
External I/O Settings	9
Calculation Settings	9
3.5 Dark Measurement	. 10
Performing Dark Measurement for the Current Integration Time and Sensitivity Range	. 10
Performing Dark Measurement for All Integration Times and Sensitivity Ranges	11
3.6 Reference Value Correction	. 12
Performing Chromaticity Correction	. 12
Performing Illuminance, Luminous Intensity, and Luminous Flux Correction	. 12
3.7 Making Measurements	. 14
Making Measurements Using the Synchronous Function	. 14
Making Measurements Using the Asynchronous Function	. 15
3.8 Acquiring Measurement Results	. 18
Measurement Results That Can Be Acquired	. 18
Chapter 4 Library Function Reference	19
4.1 Connection Functions	. 19
TmOpenDevice	. 19
TmOpenDeviceBySerial	. 19
TmCloseDevice	. 20
4.2 Measurement Conditions	. 21
TmSetMeasMode	. 21
TmGetMeasMode	. 21
TmSetIntegralTime	. 22
TmGetIntegralTime	. 22
TmSetSensitivity	. 23
TmGetSensitivity	. 23

	TmSetAverageNum	. 24
	TmGetAverageNum	. 24
	TmSetTrigType	. 24
	TmGetTrigType	. 24
	TmSetTrigDelay	. 25
	TmGetTrigDelay	. 25
	TmSetTrigTimeout	. 25
	TmGetTrigTimeout	. 25
	TmSetAutoRange	. 26
	TmGetAutoRange	. 27
	TmSetAutoRangeLevel	. 27
	TmGetAutoRangeLevel	. 27
	TmSetAcMode	. 28
	TmGetAcMode	. 28
	TmSetRefIlluminant	. 28
	TmGetRefIlluminant	. 29
	TmSetLightDistance	. 29
	TmGetLightDistance	. 29
	TmSetExtloIndexOutpTime	. 29
	TmGetExtIoIndexOutpTime	. 30
	TmSetMeasSettingAll	. 30
	TmGetMeasSettingAll	. 30
	TmInitializeMeasSettings	. 31
4.3	Measurement Execution	. 32
	TmMeasExec	. 32
	TmMeasExecAsync	. 33
	TmGetMeasStatus	. 34
	TmGetStandbyStatus	. 34
	TmCancelMeas	. 35
	TmExecDarkMeas	. 35
	TmExecDarkMeasAsync	. 36
	TmGetDarkAll	. 37
	TmSetDarkAll	. 37
	TmResetDark	. 37
4.4	Reference Value Correction	. 38
	TmExecChromaticityCorrect	. 38
	TmExecChromaticityCorrectByFile	. 39
	TmGetChromaticityCorrectValue	. 39

	TmSetChromaticityCorrectValue	39
	TmResetChromaticityCorrect	40
	TmExecIlluminanceCorrect	40
	TmGetIlluminanceCorrectValue	41
	TmSetIlluminanceCorrectValue	41
	TmResetIlluminanceCorrect	41
	TmExecLuminousFluxCorrect	41
	TmGetLuminousFluxCorrectValue	42
	TmSetLuminousFluxCorrectValue	42
	TmResetLuminousFluxCorrect	42
	TmExecLuminousIntensityCorrect	42
	TmGetLuminousIntensityCorrectValue	43
	TmSetLuminousIntensityCorrectValue	43
	TmResetLuminousIntensityCorrect	43
	TmGetUserCorrectData	44
	TmSetUserCorrectData	44
4.5	Acquiring Measurement Results	45
	TmGetIlluminanceValue	45
	TmGetLuminousIntensityValue	45
	TmGetLuminousFluxValue	45
	TmGetTristimulusValues	45
	TmGetChromaticityValue_xy	46
	TmGetChromaticityValue_uv	46
	TmGetCorrelatedColorTemperature	46
	TmGetSpecialColorRenderingIndex	46
	TmGetGeneralColorRenderingIndex	47
	TmGetDominantWaveLength	47
	TmGetMeasResultAll	47
	TmGetDetectLevel	48
4.6	Acquiring the Instrument Status	49
	TmGetSerialNo	49
	TmCheckDevice	49
	TmGetLastError	50
4.7	Structures	51
	Measurement conditions structure	51
	Reference value correction value structure	52
	Measurement results structure	53

Chapter 1 Overview

The measuring library consists of Windows software designed for use with the TM6101 LED Optical Meter. It can be used on a computer running Windows to develop software for controlling the TM6101.

Operating environment:

Supported operating systems: Windows 7 (32bit/64bit), Windows 8 (32bit/64bit),

Windows 10 (32bit/64bit)

Supported development environments: Visual Studio 2017, 2019 (Visual C++, Visual Basic,

Visual C#)

Note

Use a computer on which the target operating system operates properly. The software may not operate with sufficient speed in some operating environments.

The measuring library includes C-language header files. When using the library in a development environment other than C, for example with Visual Basic, you will need to create function declarations as necessary.

Chapter 2 Using the Measuring Library

2.1 Installing the Library

Install the software as described in "Chapter 2 Measurement Preparations" of the TM6101 LED Optical Meter Instruction Manual. You will need to install both the driver software and the PC application in order to make use of the measuring library.

2.2 Using the Library

A "Library" folder will be created in the folder into which the software was installed as described in the Instruction Manual. Copy the files in the "Library" folder to the location of your choice in your development environment.

HiLedMeas.dll DLL software
HiLedMeas.lib Library file

Tm6101Api.h Library header file

Note

The above files, driver software, and PC application software may only be redistributed for the purpose of controlling the TM6101. When distributing software you have developed, include the above files and the included installer as necessary.

Chapter 3 Controlling the TM6101

3.1 Overall Process

Open the instrument.

Use an open function to acquire a device number for the connected instrument.



Set measurement conditions.



Set measurement conditions with the measurement condition configuration function. You can either use functions that set individual measurement conditions or a function that sets all the measurement conditions at once.

Perform dark measurement.



If dark correction if not performed, you will not be able to obtain normal measured values. Be sure to perform dark measurement before making measurements.

Perform reference value correction.



In this process, the instrument's sensitivity is corrected based on reference light source spectral data and photometric values that you provide. Perform reference value correction as necessary.

Perform measurement.



Measure the target light source and perform color calculations.

Acquire the measurement results.

Acquire the measurement results.



Close the instrument.

Close the instrument.

3.2 Opening the Instrument

In order to control the instrument, it is first necessary to use an open function to open it. When the open function executes successfully, it will return at least one device number. Once the instrument has been opened, the assigned device number is used to control it.

When the instrument is opened, all measurement conditions will be initialized. Additionally, if a given instrument is closed and then reopened, it may be assigned a different device number, and all measurement conditions will be initialized.

Note

Immediately after the AC adapter and USB cable are connected to the instrument after turning on the computer's power supply, the main unit's power indicator will turn red. When the instrument is opened, the power indicator will change from red to green, and when the instrument is closed, it will change back to red.

The device number acquired when opening the instrument can only be used within the same process. The same TM6101 cannot be opened at the same time from multiple processes.

Open functions:

long TmOpenDevice(); Opens a TM6101 and acquires a device number. When multiple

instruments are connected to the computer, it is not possible to specify a

particular device to open.

long TmOpenDeviceBySerial(char* pSerial); Opens the TM6101 specified using a serial number (a 9-digit string) and

acquires a device number.

3.3 Closing the Instrument

Use the close function to close the instrument once you have completed all control operations. Once an instrument has been closed, the device number acquired with the open function can no longer be used.

Note

When the instrument is closed, its power indicator will change from green to red.

Close function:

long TmCloseDevice(long IDeviceId); Closes the TM6101 with the specified device number.

3.4 Setting Measurement Conditions

Before making measurements with the TM6101, it is necessary to set measurement conditions such as the integration time, sensitivity, and average times. It is also possible to set all the measurement conditions at once by specifying a measurement condition structure.

The current measurement conditions can be acquired using measurement condition acquisition functions.

The instrument can be reverted to the measurement conditions in effect when it was opened using the measurement condition initialization function.

<u>Note</u>

Measurement condition configuration functions cannot be used while the instrument is in the measurement standby state. The TmGetStandbyStatus function, described below, can be used to detect whether the instrument is in the measurement standby state.

The following measurement conditions must be set:

Normal Measurement Mode Settings

The TM6101 can make measurements in either of two measurement modes: normal measurement mode or AC measurement mode. The instrument is set to normal measurement mode when it is opened.

Measurement mode Set to normal measurement mode.

Integration time 0.1 / 0.5 / 1 / 2 / 4 / 8 / 10 / 16.6 / 20 / 33.3 / 40 ms

Sensitivity range High / Low Average times 1 to 100

Auto-ranging OFF / Integration time auto-ranging / Sensitivity auto-ranging

Auto-ranging level 1% to 99%

Note

When auto-ranging is enabled, the auto-ranging function will be disabled when making measurements under the following conditions:

- •AC measurement mode
- External trigger
- Dark measurement

AC Measurement Mode Settings

When making measurements in AC measurement mode, configure the following settings:

Measurement mode Set to AC measurement mode.

AC drive settings Measurement range (range 1 to 3)

Power supply frequency (60/50 Hz)

Average times (1 to 100)

*AC drive settings (measurement range, power supply frequency, and average times) are set together with the TmSetAcMode function.

External I/O Settings

Trigger type OFF / External trigger ON (rising edge) / External trigger ON

(falling edge)

Trigger delay 0 to 1,000 ms

Trigger timeout 10,000 to 1,000,000 ms

Index output time 1 to 100 ms

Note

When not using an external trigger, the trigger delay and trigger timeout settings are disabled.

Calculation Settings

Reference light CIE daylight / Blackbody radiation / Automatic selection

*Used in calculating the color rendering index.

Measuring distance 0.01 to 10.00 m

*Used in measuring luminous intensity values.

3.5 Dark Measurement

Dark-corrected measurement results are obtained by performing dark measurement before making measurements. If dark correction if not performed, you will not be able to obtain normal measured values. Be sure to perform dark measurement before making measurements. The average times can be set when performing dark measurement (average times: 1 to 100).

Note

Be sure to affix the included cap before performing dark measurement.

Either of two methods can be used to perform dark measurement: it can be performed for the current integration time and sensitivity range, or for all integration times and sensitivity ranges.

Performing Dark Measurement for the Current Integration Time and Sensitivity Range

This approach takes less time to complete, but dark measurement values are cleared whenever the integration time, sensitivity range, or measurement mode is changed. Additionally, dark measurement values are cleared when measurement is performed using auto-ranging.

Dark measurement is performed using the TmExecDarkMeas function. The function does not return until dark measurement is complete.

Performing Dark Measurement for All Integration Times and Sensitivity Ranges

By calling the function once, dark measurement is performed while automatically switching the integration time and sensitivity range. The operation takes some time to complete since dark measurement is performed for all integration times and sensitivity ranges.

When using this approach, there is no need to repeat dark measurement, even if the integration time, sensitivity range, or measurement mode is changed. Dark measurement results remain valid until the instrument is turned off. When enabling auto-ranging, perform dark measurement for all integration times and sensitivity ranges.


The library provides functions for acquiring all dark correction data, setting all dark correction data, and reverting the instrument to its state before dark measurement was performed.

Dark measurement is performed using either a synchronous or asynchronous function.

- (1) Performing dark measurement using the synchronous function Dark measurement is performed using the TmExecDarkMeas function. The function does not return until dark measurement is complete.
- (2) Performing dark measurement using the asynchronous function

 Dark measurement is performed using the TmExecDarkMeasAsync function. The function returns immediately, but <u>it is necessary to monitor the measurement status with the TmGetMeasStatus until dark measurement completes.</u>

Example of dark measurement performed using the asynchronous function:



3.6 Reference Value Correction

In this process, the instrument's sensitivity is corrected based on reference light source spectral data and photometric values that you provide. Reference value correction should be performed as necessary.

Reference value correction results are valid until the instrument is closed using the close function. In addition to functions for performing reference value correction, the library includes functions for acquiring reference value correction data, setting reference value correction data, and reverting the instrument to its state before reference value correction was performed.


Performing Chromaticity Correction

- 1. Measure the spectral characteristics of the light source for which chromaticity correction is to be performed using a standard instrument (spectral-type measuring instrument) and prepare the corresponding measurement results. You will need spectral measurement results at a 5 nm interval from 380 nm to 780 nm.
- 2. Measure the light source for which chromaticity correction is to be performed with the TM6101. For more information about the measurement procedure, see "3.7 Making Measurements" below.
- 3. Perform chromaticity correction using one of the chromaticity correction functions. The measurement results from step (2) above (from the preceding step) will be subject to correction.
- When using TmExecChromaticityCorrect, specify the spectral measurement results as the function argument.
- When using TmExecChromaticityCorrectByFile, specify the name of the file in which the spectral
 measurement results were saved as the function argument. For more information about the file
 format, see "2.8 Using Correction Functions" in the TM6101 LED Optical Meter Instruction
 Manual.

Performing Illuminance, Luminous Intensity, and Luminous Flux Correction

- 1. Measure the correction target light source with the TM6101. For more information about the measurement procedure, see "3.7 Making Measurements" below.
- 2. Perform correction using the appropriate correction function, specifying the correction target reference value as the function argument. The measurement results from step (1) above (from the preceding step) will be subject to correction.
 - •To perform illuminance correction, use TmExecIlluminanceCorrect.
 - To perform luminous intensity correction, use TmExecLuminousIntensityCorrect.
 - •To perform luminous flux correction, use TmExecLuminousFluxCorrect.


Example of reference value correction:



To measurement or other process

*Reference value correction data should be acquired and saved as necessary, for example when it will be necessary to restore correction data the next time the instrument is turned on. Processing to save reference value correction data must be implemented by the customer (for example, by saving data to a file, etc.).

Example restoration of reference value correction data:



3.7 Making Measurements

Measurement is performed using either a synchronous or asynchronous measurement function. Once measurement is complete, the measurement results can be acquired using a measurement results acquisition function.

Note


When the external trigger is enabled, external trigger monitoring is started by executing the measurement function. Once measurement using the external trigger is complete, external trigger monitoring is cancelled. To start measurement using the external trigger again, execute the measurement function again.

Making Measurements Using the Synchronous Function

Measurements are made using the TmMeasExec function. The function does not return until measurement is complete and the instrument is in the measurement standby state. The instrument enters the measurement standby state when external I/O measurement complete output changes to OFF.

When the external trigger is enabled, external trigger monitoring is started by executing the TmMeasExec function. The function does not return until either measurement completes following external trigger input or the timeout time elapses.

Example use of the synchronous function:



Making Measurements Using the Asynchronous Function

Since the asynchronous function returns immediately when measurement starts, other processing can be performed while the instrument is making measurements.

When the external trigger is enabled, external trigger monitoring is started by executing the TmMeasExec function. While the external trigger is being monitored, the monitoring state can be cancelled (i.e., the instrument can be set to the measurement standby state) by calling the TmCancelMeas function.


Once the TmMeasExecAsync function returns, the measurement status must be monitored with the TmGetMeasStatus and TmGetStandbyStatus functions.


The following procedure is used to make measurements using the asynchronous function:

- Start measurement with the TmMeasExecAsync function. The function will return as soon as the instrument starts measurement.
 - *If auto-ranging is enabled, the function will not return until auto-ranging processing completes.
- 2. Acquire the measurement status with the TmGetMeasStatus function. The TmGetMeasStatus function should be repeatedly called until measurement completes. If a value of 0xFFFFFFF is specified as the timeout time argument, the TmGetMeasStatus function will not return until measurement completes. Since measurement processing is performed internally by the TmGetMeasStatus function, be sure to verify the completion of measurement with the TmGetMeasStatus function.
- 3. Once measurement completes, the measurement results can be acquired using the library's measurement results acquisition functions. Additionally, since measurement by the sensor will have completed by this time, processing such as positioning the next measurement target can be performed.
- 4. Detect whether the instrument is in the measurement standby state with the TmGetStandbyStatus function. If the instrument is in the measurement standby state, measurement can be started with the TmMeasExecAsync function. If a value of 0xFFFFFFF is specified as the timeout time argument, the TmGetStandbyStatus function will not return until the instrument enters the measurement standby state.

Note


Once measurement starts, measurement conditions cannot be set until measurement completes and the instrument enters the measurement standby state. Do not use the measurement condition configuration functions until you verify that the instrument has entered the measurement standby state.





The following diagram illustrates the timing of instrument and library function operation. For more detailed information about instrument operation timing, see "4.2 Timing Chart" in the TM6101 LED Optical Meter Instruction Manual.

TM6101 operation timing:



- * Due to communications time requirements, it takes approximately 2 ms from the time the TmMeasExecAsync function is called until external trigger monitoring starts. Once the TmMeasExecAsync function returns, external trigger monitoring will already have started.
- * Similarly, it takes approximately 2 ms from the time measurement completes until the TmGetMeasStatus function returns, and approximately 2 ms from the time measurement complete output turns OFF until the TmGetStandbyStatus function returns (when in the standby state after setting the timeout argument to 0xFFFFFFFF).
- * The exact amount of time required for communications varies with factors such as the computer's processing capability and the operating environment being used.
- * When making measurements using the TmMeasExec function (a synchronous function), the function returns when measurement complete output changes to OFF.

3.8 Acquiring Measurement Results

Once measurement completes, measurement results such as illuminance and chromaticity values should be acquired. When the measurement function terminates normally, measurement results can be acquired. Measurement results can also be acquired together by specifying a measurement results structure.

Measurement Results That Can Be Acquired

Illuminance value

Luminous intensity value

Luminous flux value

Tristimulus values (XYZ)

Chromaticity values (xy, uv)

Correlated color temperature, Δuv

Special color rendering indexes (R1 to R15)

Average color rendering index (Ra)

Dominant wavelength

Note

Measurement results are not finalized until measurement executes successfully. Using a measurement results acquisition function while measurement is still in progress will result in an error. Measurement results can be acquired once the TmMeasExec function (a synchronous function) executes successfully, or once a measurement status of "measurement terminated successfully" is returned by the TmGetMeasStatus function.

Under some circumstances, it may be impossible to calculate measurement results despite measurement having completed successfully (indicated by a return value other than 0). Always verify measurement results acquisition function return values (look for negative chromaticity values, a Δuv value that is greater than or equal to 0.02, etc.). In such cases, the measurement results returned to the function argument will be undefined.

If measurement is canceled with the TmCancelMeas function while the external trigger is being monitored, measurement results acquisition functions will return the results of the previous measurement.

Chapter 4 Library Function Reference

4.1 Connection Functions

TmOpenDevice

Description Opens the TM6101 and acquires a device number, which is subsequently used

when performing processing with library functions.

Declaration long TmOpenDevice();

Arguments None

Return value 1 or greater: Device number 0: Failure

Note When multiple instruments are connected to the computer, this function does

not allow a specific instrument to be specified. After the instrument has been

opened, the indicator on the main unit will change from red to green.

TmOpenDeviceBySerial

Description Opens the TM6101 with the specified serial number (a 9-digit string) and

acquires a device number, which is subsequently used when performing

processing with library functions.

Declaration long TmOpenDeviceBySerial(char* pSerial);

Arguments

pSerial 9-digit serial number string (NULL-terminated)

Return value 1 or greater: Device number 0: Failure

Notes The serial number is a 9-digit string noted on the main unit or sensor unit. The

string is specified as a char (8-bit) array of ASCII characters (NULL-terminated).

Do not use 2-byte characters. After the instrument has been opened, the

indicator on the main unit will change from red to green.

Example use

"Comiguration, execution processing, etc

TmCloseDevice(lDeviceId);

TmCloseDevice

Description Closes the TM6101. If the instrument is reopened after being closed, all

measurement conditions will be initialized.

Declaration long TmCloseDevice(long IDeviceId);

Arguments

IDeviceId Device number

Return value 1: Success 0: Failure

Note After the instrument has been closed, the indicator on the main unit will change

from green to red.

4.2 Measurement Conditions

TmSetMeasMode

Description Changes the measurement mode. Measurements should usually be made in

normal measurement mode.

Declaration long TmSetMeasMode(long IDeviceId, char cMeasMode);

Arguments

IDeviceId Device number

cMeasMode Measurement mode

0: Normal measurement mode (default) 1: AC measurement mode

Return value

1: Success 0: Failure

Note

When making measurements in AC measurement mode, select AC measurement mode with the TmSetAcMode function after first setting the instrument to AC measurement mode with this function. Since the instrument defaults to normal measurement mode when it is opened, it is not necessary to

call this function when using normal measurement mode only.

Example use

· When making measurements in normal measurement mode

When making measurements in AC measurement mode

```
long lRet;
```

lRet = TmSetMeasMode(lDeviceId, 1); //AC measurement mode

lRet = TmSetAcMode(lDeviceId, 0, 1, 10); //Range 1, 50 Hz, 10 average times

TmGetMeasMode

Description Acquires the current measurement mode.

Declaration long TmGetMeasMode(long IDeviceId, char* pcMeasMode);

Arguments

IDeviceId Device number

pcMeasMode Returns the current measurement mode.

0: Normal measurement mode (default) 1: AC measurement mode

Return value 1: Success 0: Failure

TmSetIntegralTime

Description Sets the integration time. This parameter can be set when using normal

measurement mode.

Declaration long TmSetIntegralTime(long IDeviceId, char cIntTimeIndex);

Arguments

IDeviceId Device number clntTimeIndex Integration time

0: 0.1 ms 1: 0.5 ms 2: 1 ms (default) 3: 2 ms 4: 4 ms

5: 8 ms 6: 10 ms 7: 16.6 ms 8: 20 ms 9: 33.3 ms 10: 40 ms

Return value 1: Success 0: Failure

Note When AC measurement mode is the current measurement mode, switch to

normal measurement mode before calling this function. For more information about how to use this function, see the example use provided for the

TmSetMeasMode function.

TmGetIntegralTime

Description Acquires the current integration time.

Declaration long TmGetIntegralTime(long IDeviceId, char* pcIntTimeIndex);

Arguments

IDeviceId Device number

pcIntTimeIndex Returns the current integration time.

10: 40 ms

Return value 1: Success 0: Failure

Note The optimal integration time is set automatically when performing

measurements with integration time auto-ranging. This function can be used to acquire the current integration time setting. For an example of how

to use this function, see the TmSetAutoRange function.

TmSetSensitivity

Description Sets the sensitivity range. This parameter can be set in normal

measurement mode.

Declaration long TmSetSensitivity(long IDeviceId, char nCh, char cSens);

Arguments

IDeviceIdDevice numbernChSensor number

Specify value from 0 to 15, corresponding to sensors 1 through 16.

cSens Sensitivity range

0: High sensitivity 1: Low sensitivity

Return value

1: Success 0: Failure

Note

When AC measurement mode is the current measurement mode, switch to normal measurement mode before calling this function. For more information about how to use this function, see the example use provided for the TmSetMeasMode function. The instrument makes measurements using 16 optical sensors, each of which has different optical characteristics. Sensitivity range settings are made in pairs, with corresponding sensors sharing the same sensitivity range setting. For example, if the sensitivity range for sensor 1 is set to low, the sensitivity range for sensor 2 will also be set to low. (Conversely, if the sensitivity range for sensor 2 is set to high, the sensitivity range for sensor 1 will also be set to high.)

Sensor 1	Sensor 3	Sensor 5	Sensor 7	Sensor 9	Sensor 11	Sensor 13	Sensor 15
Sensor 2	Sensor 4	Sensor 6	Sensor 8	Sensor 10	Sensor 12	Sensor 14	Sensor 16
High/Low	High/Low	High/Low	High/Low	High/Low	High/Low	High/Low	High/Low

TmGetSensitivity

Description Acquires the current sensitivity range.

Declaration long TmGetSensitivity(long IDeviceId, char nCh, char* pcSens)

Arguments

IDeviceId Device numbernCh Sensor number

Specify value from 0 to 15, corresponding to sensors 1 through 16.

pcSens Returns the current sensitivity range.

0: High sensitivity 1: Low sensitivity

Return value 1: Success 0: Failure

Note The optimal sensitivity range is set automatically when performing

measurements with sensitivity range auto-ranging. This function can be used to acquire the current sensitivity range setting. For an example of how

to use this function, see the TmSetAutoRange function.

TmSetAverageNum

Description Sets the average times. This parameter can be set in normal measurement

mode.

Declaration long TmSetAverageNum(long IDeviceId, long IAveNum);

Arguments

IDeviceId Device number
IAveNum Average times

1: No averaging (default) 2 to 100: Average times

Return value 1: Success 0: Failure

TmGetAverageNum

Description Acquires the current average times.

Declaration long TmGetAverageNum(long IDeviceId);

Arguments

IDeviceId Device number

Return value Average times: 1 to 100 (0: Failure)

Note To acquire the average times in AC measurement mode, use the

TmGetAcMode function.

TmSetTrigType

Description Configures the external trigger.

Declaration long TmSetTrigType(long lDeviceId, char cTrigType);

Arguments

IDeviceId Device number

cTrigType 0: External trigger OFF (default) 1: External trigger ON (rising edge)

2: External trigger ON (falling edge)

Return value 1: Success 0: Failure

Note When the external trigger is set to ON, external trigger monitoring is started

by executing the TmExecMeas function.

TmGetTrigType

Description Acquires the current external trigger setting.

Declaration long TmGetTrigType(long lDeviceId, char* pcTrigType);

Arguments

IDeviceId Device number

pcTrigType Returns the current external trigger setting.

0: External trigger OFF (default) 1: External trigger ON (rising edge)

2: External trigger ON (falling edge)

Return value 1: Success 0: Failure

TmSetTrigDelay

Description Sets the trigger delay.

Declaration long TmSetTrigDelay(long IDeviceId, long IDelay);

Arguments

IDeviceId Device number

IDelay Trigger delay (ms): 0 to 1,000 (default: 0 ms)

Return value 1: Success 0: Failure

Note The trigger delay setting is valid when the external trigger is ON. The trigger

delay does not function when the external trigger is OFF.

TmGetTrigDelay

Description Acquires the current trigger delay setting.

Declaration long TmGetTrigDelay(long IDeviceId, long* pIDelay);

Arguments

IDeviceId Device number

plDelay Returns the current trigger delay setting (ms).

Return value 1: Success 0: Failure

TmSetTrigTimeout

Description Sets the external trigger timeout time.

Declaration long TmSetTrigTimeout(long IDeviceId, long ITimeout);

Arguments

IDeviceId Device number

Trigger timeout time (ms): 10,000 to 1,000,000 (default: 100,000 ms)

Return value 1: Success 0: Failure

Note Once external trigger monitoring is started with a measurement function,

measurement will be forcibly terminated if no external trigger has been input

when the trigger timeout time elapses.

TmGetTrigTimeout

Description Acquires the current external trigger timeout time.

Declaration long TmGetTrigTimeout(long IDeviceId, long* plTimeout);

Arguments

IDeviceId Device number

plTimeout Returns the trigger timeout time (ms).

Return value 1: Success 0: Failure

TmSetAutoRange

Description Configures auto-ranging.

Declaration long TmSetAutoRange(long IDeviceId, char cAutoRangeType);

Arguments

IDeviceId Device numbercAutoRangeType 0: Off (default)

1: Integration time auto-ranging

2: Sensitivity auto-ranging

Return value 1: Success 0: Failure

Note Auto-ranging cannot be used in AC measurement mode or when the

external trigger is enabled. The optimal integration time or sensitivity range is automatically set when making measurements using auto-ranging. The TmGetIntegralTime and TmGetSensitivity functions can be used to acquire

the current settings.

Example use

```
long lRet;
char cIntegralTime;
                        //Integration time
char cSens[16]; //Sensitivity range
lRet = TmSetAutoRange(lDeviceId, 1);
                                         //Integration time auto-ranging
lRet = TmMeasExec();
                                         //Make measurement using integration
                                         time auto-ranging
lRet = TmGetIntegralTime(lDeviceId, &cIntegralTime);
                                                         //Acquire integration time
lRet = TmSetAutoRange(lDeviceId,2);
                                         //Sensitivity auto-ranging
IRet = TmMeasExec();
                                         //Make measurement using sensitivity
                                         auto-ranging
for (char nCh = 0; nCh < 16; nCh++) {
      lRet = TmGetSensitivity(lDeviceId, nCh, &cSens[nCh]); //Acquire sensitivity
                                                                range
}
```

TmGetAutoRange

Description Acquires the auto-ranging setting.

Declaration long TmGetAutoRange(long IDeviceId, char* pcAutoRangeType);

Arguments

IDeviceId Device number

pcAutoRangeType Returns the auto-ranging setting.

0: Off (default)

1: Integration time auto-ranging

2: Sensitivity auto-ranging

Return values 1: Success 0: Failure

TmSetAutoRangeLevel

Description Sets the auto-ranging detection level upper and lower limits.

Declaration long TmSetAutoRangeLevel(long IDeviceId, char cLevelHigh, char cLevelLow);

Arguments

IDeviceId Device number

cLevelHigh Auto-ranging upper limit (%): 1 to 99 (default: 90%) cLevelLow Auto-ranging lower limit (%): 1 to 99 (default: 10%)

Return values 1: Success 0: Failure

Note When using integration time auto-ranging, the integration time is automatically

adjusted so that the detection levels of all sensors are greater than or equal to the lower limit while not exceeding the upper limit. When using sensitivity auto-ranging, the sensitivity (high/low) is automatically adjusted so that the detection levels of individual sensors are greater than or equal to the lower limit while not exceeding the upper limit. In order for auto-ranging to function properly, the upper limit should be set to at least twice the lower limit (for example, if the lower limit is 30%, use an upper limit of at least 60%). Setting either cLevelHigh or cLevelLow to 0 causes the settings to revert to their default values (upper

limit of 90%, lower limit of 10%).

TmGetAutoRangeLevel

Description Acquires the auto-ranging detection level upper and lower limits.

Declaration long TmGetAutoRangeLevel(long IDeviceId, char* pcLevelHigh, char*

pcLevelLow);

Arguments

IDeviceId Device number

pcLevelHigh Returns the auto-ranging upper limit (%).
pcLevelLow Returns the auto-ranging lower limit (%).

Return values 1: Success 0: Failure

TmSetAcMode

Description Configures AC measurement mode.

Declaration long TmSetAcMode(long IDeviceId, char cAcRange, char cAcPlc, long

IAveNum);

Arguments

IDeviceId Device number

cAcRange AC measurement mode range

0: Range 1 (default) 1: Range 2 2: Range 3

cAcPlc Power supply frequency 0: 60 Hz 1: 50 Hz (default)

IAveNum AC measurement mode averaging times: 1 to 100 (default: 1)

Return values 1: Success 0: Failure

Note Use this function to make settings after switching to AC measurement mode

with the TmSetMeasMode function.

TmGetAcMode

Description Acquires AC measurement mode settings.

Declaration long TmGetAcMode(long IDeviceId, char* pcAcRange, char* pcAcPlc,

long* plAveNum);

Arguments

IDeviceId Device number

pcAcRange Returns the AC measurement mode range.

0: Range 1 1: Range 2 2: Range 3

pcAcPlc Returns the power supply frequency.

0: 60 Hz 1: 50 Hz

plAveNum Returns the AC measurement mode averaging times. 1 to 100

Return value 1: Success 0: Failure

TmSetRefIlluminant

Description Sets the reference light source to use for color rendering index calculations.

Declaration long TmSetRefIlluminant(long IDeviceId, char cType);

Arguments

IDeviceId Device number

cType 0: CIE daylight 1: Blackbody radiation

2: Automatic selection (blackbody radiation < 5,000 K ≤ CIE daylight) (default)

Return value 1: Success 0: Failure

TmGetRefIlluminant

Description Acquires the reference light source to use for color rendering index

calculations.

Declaration long TmGetRefIlluminant(long lDeviceId, char* pcSet);

Arguments

IDeviceId Device number

pcSet Returns the reference light source.

0: CIE daylight 1: Blackbody radiation 2: Automatic selection

Return value 1: Success 0: Failure

Note

TmSetLightDistance

Description Sets the light measurement distance to use when calculating the luminous

intensity.

Declaration long TmSetLightDistance(long lDeviceId, double dDistance);

Arguments

IDeviceId Device number

dDistance Light measurement distance (m): 0.01 to 10.00 (default: 0.01 [m])

Return value 1: Success 0: Failure

TmGetLightDistance

Description Acquires the light measurement distance to use when calculating the luminous

intensity.

Declaration long TmGetLightDistance(long IDeviceId, double* pdDistance);

Arguments

IDeviceId Device number

pdDistance Returns the light measurement distance (m).

Return value 1: Success 0: Failure

TmSetExtIoIndexOutpTime

Description Sets the on time for external I/O measurement complete output (index output).

Declaration long TmSetExtloIndexOutpTime(long IDeviceId, DWORD dwTimeMsec);

Arguments

IDeviceId Device number

dwTimeMsec On time (ms): 1 to 100 (default: 1 ms)

Return value 1: Success 0: Failure

Note Measurement complete output is disabled during dark measurement.

TmGetExtIoIndexOutpTime

Description Returns the on time for external I/O measurement complete output (index

output).

Declaration long TmGetExtloIndexOutpTime(long IDeviceId, DWORD* pdwTimeMsec)

Arguments

IDeviceId Device number

pdwTimeMsec Returns the on time (ms).

Return value 1: Success 0: Failure

TmSetMeasSettingAll

Description Sets all measurement conditions at once.

Declaration long TmSetMeasSettingAll(long IDeviceId, TM_MEAS_SET stMeasSet);

Arguments

IDeviceId Device number

stMeasSet Specify a measurement conditions structure with settings for all member

variables.

Return value 1: Success 0: Failure

Note Specify all measurement conditions in the TM_MEAS_SET structure. This

functionality is used to reconfigure settings acquired the last time a TM6101 was connected using the TmGetMeasSettingAll function the next time the instrument

is connected.

Example use

TM MEAS SET stMeasSet; //Measurement conditions structure

stMeasSet.dwMeasMode = 0; //Normal measurement mode

stMeasSet. dwIntTime = 2; //Integration time: 1 ms

//Continue setting all member variables

.

TmSetMeasSettingAll(lDeviceId, stMeasSet); //Set all measurement conditions

TmGetMeasSettingAll

Description Acquires all current measurement settings at once.

Declaration long TmGetMeasSettingAll(long IDeviceId, TM_MEAS_SET* pstMeasSet);

Arguments

IDeviceId Device number

pstMeasSet Returns a measurement conditions structure. Specify a pointer to a

measurement conditions structure.

Return value 1: Success 0: Failure

Example use

TM_MEAS_SET stMeasSet; //Measurement conditions structure

TmSetMeasSettingAll(lDeviceId, &stMeasSet); //Acquire all measurement conditions

at once

TmInitializeMeasSettings

Description Initializes measurement conditions.

Declaration long TmInitializeMeasSettings(long IDeviceId);

Arguments

IDeviceId Device number

Return value 1: Success 0: Failure

Note See individual function descriptions for return values. Initialization cannot be

performed while measurement is in progress.

4.3 Measurement Execution

TmMeasExec

Description Performs measurement. When the external trigger is enabled, starts monitoring

of the external trigger. The function does not return until either measurement

completes or the trigger timeout time elapses.

Declaration long TmMeasExec(long IDeviceId);

Arguments

IDeviceId Device number

Return value 1: Success 0: Failure

Note Measurement results can be acquired once measurement completes.

Example use

•Make 10 measurements and terminate:

```
long lDeviceId = TmOpenDevice ();
                                            //Open the TM6101 device
if (IDeviceId \le 0) {
         //Error processing
}
long lRet;
double x, y;
lRet = TmSetAutoRange(lDeviceId,1);
                                                     //Integration time auto-ranging
         //Use default values for other measurement conditions
lRet = TmExecDarkMeas(lDeviceId, 10, 1); //Perform dark measurement for all ranges
                                             (averaging times: 10)
for (long \, nNum = 0; \, nNum < 10; \, nNum++) 
    lRet = TmMeasExec(lDeviceId);
                                                     //Perform measurement using
                                                      integration time auto-ranging
    lRet = TmGetChromaticityValue_xy(lDeviceId, &x,&y);
                                                              /Acquire xy chromaticity
                                                              values
}
    //Processing to display measurement results, etc.
TmCloseDevice(lDeviceId);
                                   //Close device
```

TmMeasExecAsync

Description Starts measurement. When the external trigger is enabled, starts monitoring of

the external trigger. The function returns immediately.

Declaration long TmMeasExecAsync(long IDeviceId);

Arguments

IDeviceId Device number

Return value 1: Success 0: Failure

Note Be sure to verify the completion of measurement with the TmGetMeasStatus

function before acquiring measurement results. Measurement results can be acquired once measurement completes. Call TmCancelMeas to terminate monitoring of the external trigger. If measurement is canceled with the TmCancelMeas function while monitoring of the external trigger is in progress, the measurement results acquisition function will return results for the previous measurement. Before starting the next measurement, verify that the instrument is in the measurement standby state with the TmGetStandbyStatus

function and then start measurement with TmMeasExecAsync.

Example use

•Make 10 measurements with the asynchronous function:

```
long lRet;
double x, y;
                          //Chromaticity values
DWORD dwStatus;
                          //Measurement status
    //Make measurements using default measurement conditions
for (\log nNum = 0; nNum < 10; nNum++) {
                                                    //Make 10 measurements
    lRet = TmMeasExecAsync (lDeviceId);
                                                    // Start measurement
                                                    asynchronously
    do {
        lRet = TmGetMeasStatus(lDeviceId, &dwStatus, 0); //Acquire measurement
                                                              status
    } while (dwStatus == 0);
                                  //If measurement in progress, acquire measurement
                                   status repeatedly
    //Acquire measurement results
    lRet = TmGetChromaticityValue_xy(lDeviceId, &x,&y);
    do {
        lRet = TmGetStandbyStatus(lDeviceId, &dwStatus, 0); //Detect standby state
    \} while (dwStatus == 0);
                                  //Acquire status repeatedly until the standby state is
                                   detected
}
```

TmGetMeasStatus

Description Acquires the current measurement status.

Declaration long TmGetMeasStatus(long IDeviceId, DWORD* pdwStatus,

DWORD dwMilliseconds):

Arguments

IDeviceId Device number

pdwStatus Returns the measurement status.

0: Measurement or trigger monitoring in progress

1: Measurement completed normally

2: Measurement terminated with an error

dwMilliseconds Timeout time (ms): 0 to 0xFFFFFFF

The function returns when the timeout time elapses or measurement completes. Specifying 0 causes the function to return immediately. Specifying 0xFFFFFFFcauses the function to not return until measurement completes.

Return value

1: Success 0: Failure

Note

When starting measurement with TmMeasExecAsync or TmExecDarkMeasAsync, execute this function until it generates a return value of 1 or 2. To forcibly terminate measurement or trigger monitoring, call TmCancelMeas. When measurement is forcibly terminated with the TmCancelMeas function, the measurement status is returned as 2 (measurement terminated with an error). When external trigger monitoring is terminated, the measurement status is returned as 1 (measurement completed normally). For more information about how to use this function, see the TmMeasExecAsync function.

TmGetStandbyStatus

Description Detects the measurement standby state.

Declaration long TmGetStandbyStatus(long IDeviceId, DWORD* pdwStatus,

DWORD dwMilliseconds);

Arguments

IDeviceId Device number

pdwStatus Returns the measurement standby state.

0: Measurement in progress

1: Standby

dwMilliseconds Timeout time (ms): 0 to 0xFFFFFFF

The function returns when the timeout time elapses or the instrument changes to the measurement standby state. Specifying 0 causes the function to return immediately. Specifying 0xFFFFFFFcauses the function to not return until the

instrument changes to the measurement standby state.

Return value

1: Success 0: Failure

Note

When the measurement standby state is returned as 1 (standby state), can be started with the TmMeasExecAsync TmDarkMeasExecAsync function. For more information about how to use this function, see the TmMeasExecAsync function.

TmCancelMeas

Description Cancels measurement processing when performing measurement

asynchronously.

Declaration long TmCancelMeas(long IDeviceId);

Arguments

IDeviceId Device number

Return value 1: Success 0: Failure

Note Cancels measurement processing started with the TmMeasExecAsync or

TmExecDarkMeasAsync function. When external trigger monitoring is in progress, terminates external trigger monitoring. After calling this function, monitor the measurement status with TmGetMeasStatus until measurement processing completes. This function is not normally used. Instead, acquire the measurement status with the TmGetMeasStatus function and wait for

measurement to complete.

TmExecDarkMeas

Description Performs dark measurement. The function does not return until dark

measurement completes.

Declaration long TmExecDarkMeas(long IDeviceId, unsigned int nAveNum,

char nAllRange);

Arguments

IDeviceId Device number

nAveNum Averaging times: 1 to 100

nAllRange 0: Performs dark measurement for the current integration time and sensitivity

range.

1: Performs dark measurement for all integration times, sensitivity ranges, and

AC measurement ranges.

Return value

1: Success 0: Failure

Note

Dark measurement is disabled while the external trigger is enabled. Additionally, measurement complete output (index output) is not generated after dark measurement completes. Until dark measurement is performed after opening an instrument with TmOpenDevice or a similar function, the default dark values (the values set at the time of shipment) are applied to measurement results. It is recommended to perform dark measurement every time an instrument is connected. If dark measurement is performed for the current integration time and sensitivity range, it will need to be repeated if the integration time, sensitivity range, or measurement mode is changed. For more information about how to use this function, see the TmMeasExec function.

TmExecDarkMeasAsync

Description Performs dark measurement for all integration times, sensitivity ranges, and

AC measurement ranges. Processing is performed asynchronously, so the

function returns immediately.

Declaration long TmExecDarkMeasAsync(long IDeviceId, unsigned int nAveNum);

Arguments

IDeviceId Device number

nAveNum Averaging times: 1 to 100 **Return value** 1: Success 0: Failure

Note Be sure to verify that dark measurement has completed with the

TmGetMeasStatus function. Dark measurement is disabled while the external trigger is enabled. Additionally, measurement complete output (index output) is not generated after dark measurement completes. Until dark measurement is performed after opening an instrument with TmOpenDevice or a similar function, the default dark values (the values set at the time of shipment) are applied to measurement results. It is recommended to perform dark

measurement every time an instrument is connected.

Example use

long lRet;

DWORD dwStatus; //Measurement status

do {

 $lRet = TmGetMeasStatus(lDeviceId, \&dwStatus, 0); \\ //Acquire measurement \\ status$

} while (dwStatus == 0); //Repeatedly acquire the measurement status while measurement is in progress

do {

} while (dwStatus == 0); //Repeatedly acquire the status until the instrument changes to the standby state

//// End of dark measurement processing for all ranges ////

TmGetDarkAll

Description Acquires dark values for all normal measurement mode integration times,

sensitivity ranges, and AC measurement ranges.

Declaration long TmGetDarkAll(long IDeviceId, DWORD dwDarkDataAll[]);

Arguments

IDeviceId Device number

dwDarkDataAll[] Specify an array for storing the dark values.

Specify DWORD dwDarkDataAll[448] (DWORD×448).

Return value 1: Success 0: Failure

Note Dark values can be acquired after performing dark measurement for all

integration times and sensitivity ranges with the TmExecDarkMeas or

TmExecDarkMeasAsync function.

Example use

dwDarkDataAll[448]; //Array for storing dark results

results

TmSetDarkAll

Description Sets dark values for all integration times, sensitivity ranges, and AC

measurement ranges.

Declaration long TmSetDarkAll(long IDeviceId, DWORD dwDarkDataAll[]);

Arguments

IDeviceId Device number

dwDarkDataAll[] Specify an array storing the desired dark values.

Specify DWORD dwDarkDataAll[448] (DWORD×448).

Return value 1: Success 0: Failure

Note This function is used to reconfigure the TM6101 with the dark values acquired

using TmGetDarkAll the last time the instrument was connected.

TmResetDark

Description Clears dark measurement results and resets the instrument to its state before

dark measurement was performed.

Declaration long TmResetDark(long lDeviceId);

Arguments

IDeviceId Device number

Return value 1: Success 0: Failure

Note Executing this function causes the default dark values (the values set at the

time of shipment) to be applied to measurement results.

4.4 Reference Value Correction

TmExecChromaticityCorrect

Description Performs chromaticity correction. Specify the spectral characteristics data for

the chromaticity correction target light source as an array.

Declaration long TmExecChromaticityCorrect(long IDeviceId, double dSpectramData[]);

Arguments

IDeviceId Device number

dSpectramData [] Specify an array storing the spectral characteristics data.

Data is required every 5 nm for 380 nm to 780 nm (81 data points). Specify

double dData[81] (double×81).

Return value 1: Success 0: Failure

Note The latest measurement results are applied to chromaticity correction. Before

performing chromaticity correction, measure the chromaticity correction target

light source.

Example use

long lRet;

double dSpectramData [81]; //Spectral characteristics data for the chromaticity

correction target light source

for (int nDataNo = 0; nDataNo < 81; nDataNo++)

dSpectramData [81] = ····; //Register the spectral data

lRet = TmSetAutoRange(lDeviceId,1); //Integration time auto-ranging

lRet = TmSetAverageNum(lDeviceId,5); //Averaging times; 5

// Make measurements using default measurement conditions

lRet = TmExecDarkMeas(lDeviceId, 10, 1); //Perform dark measurement for all ranges

(averaging times: 10)

//Measure the correction target light source

lRet = TmMeasExec(lDeviceId); //Perform measurement using integration

time auto-ranging

//Perform chromaticity correction

lRet = TmExecChromaticityCorrect(lDeviceId, dSpectramData);

//Perform measurement and other processing

TmExecChromaticityCorrectByFile

Description Performs chromaticity correction. Specify a CSV file storing the spectral

characteristics data for the chromaticity correction target light source.

Declaration long TmExecChromaticityCorrectByFile(long lDeviceId, char* cFilePath);

Arguments

IDeviceId Device number

cFilePath Specify the full pathname for a CSV file storing the spectral characteristics

data. This file must contain wavelength and spectral characteristics data for

380 nm to 780 nm (every 5 nm) (81 data points).

Return value 1: Success 0: Failure

Note For more information about the file format, see the instrument's instruction

manual. The latest measurement results are applied to chromaticity correction. Before performing chromaticity correction, measure the chromaticity correction

target light source.

TmGetChromaticityCorrectValue

Description Acquires chromaticity correction values.

Declaration long TmGetChromaticityCorrectValue(long IDeviceId, double dData[]);

Arguments

IDeviceId Device number

dData[] Specify an array for storing the chromaticity correction values (double×16).

Specify double dData[16] (double×16).

Return value 1: Success 0: Failure (or correction not performed)

TmSetChromaticityCorrectValue

Description Sets chromaticity correction values.

Declaration long TmSetChromaticityCorrectValue(long IDeviceId, double dData[]);

Arguments

IDeviceId Device number

dData[] Specify an array storing the chromaticity correction values (double×16).

Specify double dData[16] (double×16).

Return value 1: Success 0: Failure

Note This function is used to reconfigure the TM6101 with correction values

acquired using the TmSetChromaticityCorrectValue function the last time the

instrument was connected.

TmResetChromaticityCorrect

Description When chromaticity correction has been performed, clears the chromaticity

correction values and reverts the instrument to its state before chromaticity

correction was performed.

Declaration long TmResetChromaticityCorrect(long IDeviceId);

Arguments

IDeviceId Device number

Return value 1: Success 0: Failure

TmExecIlluminanceCorrect

Description Performs illuminance correction. Specify the illuminance value for the

correction target light source.

Declaration long TmExecllluminanceCorrect(long IDeviceId, double dllluminance);

Arguments

IDeviceId Device number

dllluminance Correction target illuminance value (lx)

Return value 1: Success 0: Failure

Note The latest measurement results are applied to illuminance correction. Before

performing illuminance correction, measure the illuminance correction target

light source.

Example use

long lRet;

lRet = TmSetAutoRange(lDeviceId,1); //Integration time auto-ranging

lRet = TmSetAverageNum(lDeviceId,5); //Averaging times: 5

// Make measurements using default measurement conditions

lRet = TmExecDarkMeas(lDeviceId, 10, 1); //Perform dark measurement for all ranges

(averaging times: 10)

//Measure the correction target light source

lRet = TmMeasExec(lDeviceId); //Perform measurement using integration

time auto-ranging

//Perform illuminance correction

lRet = TmExecIlluminanceCorrect (lDeviceId, 1000); //Correct using 1,000 lx

// Perform measurement and other processing

TmGetIlluminanceCorrectValue

Description Acquires the illuminance correction value.

Declaration long TmGetllluminanceCorrectValue(long IDeviceId, double* pdData);

Arguments

IDeviceId Device number

pdData Returns the illuminance correction value.

Return value 1: Success 0: Failure (or correction not performed)

TmSetIlluminanceCorrectValue

Description Sets the illuminance correction value.

Declaration long TmSetIlluminanceCorrectValue(long IDeviceId, double dData);

Arguments

IDeviceId Device number

dData Illuminance correction value **Return value** 1: Success 0: Failure

Note This function is used to reconfigure the TM6101 with the correction value

acquired using TmGetIlluminanceCorrectValue the last time the instrument

was connected.

TmResetIlluminanceCorrect

Description When illuminance correction has been performed, clears the illuminance

correction value and reverts the instrument to its state before illuminance

correction was performed.

Declaration long TmResetllluminanceCorrect(long IDeviceId);

Arguments

IDeviceId Device number

Return value 1: Success 0: Failure

TmExecLuminousFluxCorrect

Description Performs luminous flux correction. Specify the luminous flux value for the

correction target light source.

Declaration long TmExecLuminousFluxCorrect(long IDeviceId, double dLuminousFlux);

Arguments

IDeviceId Device number

dLuminousFlux Correction target luminous flux value (lm)

Return value 1: Success 0: Failure

Note The latest measurement results are applied to luminous flux correction. Before

performing luminous flux correction, measure the luminous flux correction target light source. For more information about how to use this function, see the TmExecIlluminanceCorrect function. The same processing sequence is

used as for illuminance correction.

TmGetLuminousFluxCorrectValue

Description Acquires the luminous flux correction value.

Declaration long TmGetLuminousFluxCorrectValue(long IDeviceId, double* pdData);

Arguments

IDeviceId Device number

pdData Returns the luminous flux correction value.

Return value 1: Success 0: Failure (or correction not performed)

TmSetLuminousFluxCorrectValue

Description Sets the luminous flux correction value.

Declaration long TmSetLuminousFluxCorrectValue(long IDeviceId, double dData);

Arguments

IDeviceId Device number

dData Luminous flux correction value

Return value 1: Success 0: Failure

Note This function is used to reconfigure the TM6101 with the correction value

acquired using the TmGetLuminousFluxCorrectValue function the last time the

instrument was connected.

TmResetLuminousFluxCorrect

Description When luminous flux correction has been performed, clears the luminous flux

correction value and reverts the instrument to its state before luminous flux

correction was performed.

Declaration long TmResetLuminousFluxCorrect(long IDeviceId);

Arguments

IDeviceId Device number

Return value 1: Success 0: Failure

TmExecLuminousIntensityCorrect

Description Performs luminous intensity correction. Specify the luminous intensity value for

the correction target light source.

Declaration long TmExecLuminousIntensityCorrect(long IDeviceId,

double LuminousIntensity);

Arguments

IDeviceId Device number

LuminousIntensity Correction target luminous intensity value (cd)

Return value 1: Success 0: Failure

Note The latest measurement results are applied to luminous intensity correction.

Before using this function, set the distance to the light source with the TmSetLightDistance function. Before performing luminous intensity correction, measure the luminous intensity correction light source. For more information about how to use this function, see the TmExecIlluminanceCorrect function.

The same processing sequence is used as for illuminance correction.

TmGetLuminousIntensityCorrectValue

Description Acquires the luminous intensity correction value.

Declaration long TmGetLuminousIntensityCorrectValue(long IDeviceId, double* pdData);

Arguments

IDeviceId Device number

pdData Returns the luminous intensity correction value.

Return value 1: Success 0: Failure (or correction not performed)

TmSetLuminousIntensityCorrectValue

Description Sets the luminous intensity correction value.

Declaration long TmSetLuminousIntensityCorrectValue(long lDeviceId, double dData);

Arguments

IDeviceId Device number

dData Luminous intensity correction value

Return value 1: Success 0: Failure

Note This function is used to reconfigure the TM6101 with the correction value

acquired using the TmGetLuminousIntensityCorrectValue function the last

time the instrument was connected.

TmResetLuminousIntensityCorrect

Description When luminous intensity correction has been performed, clears the luminous

intensity correction value and reverts the instrument to its state before

luminous intensity correction was performed.

Declaration long TmResetLuminousIntensityCorrect(long IDeviceId);

Arguments

IDeviceId Device number

TmGetUserCorrectData

Description Acquires all reference value correction values (chromaticity correction values,

illuminance correction value, luminous intensity correction value, and luminous

flux correction value) at once.

Declaration long TmGetUserCorrectData(long IDeviceId,

TM_USER_CORRECT_DATA* pstUserCorrect);

Arguments

IDeviceId Device number

pstUserCorrect Returns correction values.

Specify a TM_USER_CORRECT_DATA structure.

Return value 1: Success 0: Failure

Example use

TM_USER_CORRECT_DATA stUserCorrect); //Reference value correction

structure

TmGetUserCorrectData (lDeviceId, &stUserCorrect); //Acquires all correction

values at once.

TmSetUserCorrectData

Description

Declaration long TmSetUserCorrectData(long IDeviceId,

TM USER CORRECT DATA stUserCorrect);

Arguments

IDeviceId Device number

stUserCorrect Specify a TM_USER_CORRECT_DATA structure storing the correction

values.

4.5 Acquiring Measurement Results

TmGetIlluminanceValue

Description Acquires the illuminance value.

Declaration long TmGetIlluminanceValue(long IDeviceId, double* pdData);

Arguments

IDeviceId Device number

pdData Returns the illuminance value (lx).

Return value 1: Success 0: Failure

TmGetLuminousIntensityValue

Description Acquires the luminous intensity value.

Declaration long TmGetLuminousIntensityValue(long IDeviceId, double* pdData);

Arguments

IDeviceId Device number

pdData Returns the luminous intensity value (cd).

Return value 1: Success 0: Failure

TmGetLuminousFluxValue

Description Acquires the luminous flux value.

Declaration long TmGetLuminousFluxValue(long lDeviceId, double* pdData);

Arguments

IDeviceId Device number

pdData Returns the luminous flux value (lm).

Return value 1: Success 0: Failure

TmGetTristimulusValues

Description Acquires tristimulus values.

Declaration long TmGetTristimulusValues(long IDeviceId,

double* pX, double* pY, double* pZ);

Arguments

IDeviceId Device number

pX, pY, pZ Acquires the tristimulus values (x, y, and z).

TmGetChromaticityValue_xy

Description Acquires the chromaticity values (x and y).

Declaration long TmGetChromaticityValue_xy(long IDeviceId, double* pX, double* pY);

Arguments

IDeviceId Device number

pX, pY Returns the chromaticity values (x and y).

Return value 1: Success 0: Failure

TmGetChromaticityValue_uv

Description Acquires the chromaticity values (u and v).

Declaration long TmGetChromaticityValue_uv(long IDeviceId, double* pU, double* pV);

Arguments

IDeviceId Device number

pU, pV Returns the chromaticity values (u and v).

Return value 1: Success 0: Failure

TmGetCorrelatedColorTemperature

Description Acquires the correlated color temperature and Δuv value.

Declaration long TmGetCorrelatedColorTemperature(long IDeviceId, double* pdTcp,

double* pdDUV);

Arguments

IDeviceId Device number

pdTcp Returns the correlated color temperature (K).

pdDUV Returns the ∆uv value. **Return value** 1: Success 0: Failure

Note If the absolute value of the Δuv value is greater than 0.02, the correlated color

temperature measurement result will indicate an error.

TmGetSpecialColorRenderingIndex

Description Acquires the special color rendering index Ri.

Declaration long TmGetSpecialColorRenderingIndex(long IDeviceId, char nTestColorNo,

double* pdData);

Arguments

IDeviceId Device number

nTestColorNo Specify the test color (0 to 14, for test colors 1 to 15).

pdData Returns the special color rendering index Ri.

TmGetGeneralColorRenderingIndex

Description Acquires the general color rendering index Ra.

Declaration long TmGetGeneralColorRenderingIndex(long IDeviceId, double* pdData);

Arguments

IDeviceId Device number

pdData Returns the average color rendering index Ra.

Return value 1: Success 0: Failure

TmGetDominantWaveLength

Description Acquires the dominant wavelength and excitation purity.

Declaration long TmGetDominantWaveLength(long IDeviceId, double* pdDomiLen,

double* pdPurity);

Arguments

IDeviceId Device number

pdDomiLen Returns the dominant wavelength (nm).

pdPurity Returns the excitation purity (%).

Return value 1: Success 0: Failure

TmGetMeasResultAll

Description Acquires all measurement results at once.

Declaration long TmGetMeasResultAll(long IDeviceId,

TM_MEAS_RESULT* pstMeasResult);

Arguments

IDeviceId Device number

pstMeasResult Returns the measurement results in a TM_MEAS_RESULT structure.

Return value 1: Success 0: Failure

Note Measurement results and an indication of whether each result is valid or

invalid are stored in the TM_MEAS_RESULT structure.

Example use

TM_MEAS_RESULT stMeasResult; //Measurement results structure

//Acquire all measurement results at once

long lRet = TmGetMeasResultAll (lDeviceId, & stMeasResult);

TmGetDetectLevel

Description Acquires the detection level for each of the instrument's 16 sensors.

Declaration long TmGetDetectLevel(long IDeviceId, char nCh, double* pdLevel);

Arguments

IDeviceId Device number

nCh Sensor number (specify 0 to 15, for sensors 1 through 16).

pdLevel Returns the detection level.

Detection level: 0.00 to 1.00

(0.00: Underflow 1.00: Overflow)

Return value 1: Success 0: Failure

Example use

4.6 Acquiring the Instrument Status

TmGetSerialNo

Description Acquires the serial number of a previously opened TM6101.

Declaration long TmGetSerialNo(long IDeviceId, char* pSerial, DWORD nByteSize);

Arguments

IDeviceId Device number

pSerial Returns the serial number as a string. Specify a char array of at least 16 bytes.

nByteSize Number of bytes in the array specified with pSerial

Return value Number of characters in the acquired serial number 0: Failure

Note Returns an ASCII string (NULL-terminated) to the char array (8-bit).

TmCheckDevice

Description Acquires the status of a previously opened TM6101.

Declaration long TmCheckDevice(long IDeviceId);

Arguments

IDeviceId Device number

Return value 1: No error 0: Error

Note This function returns a value of 0 (error) if an error has occurred with either the

USB connection or the connection between the main unit and the sensor unit.

Verify the nature of the error with the TmGetLastError function.

TmGetLastError

Description Acquires error information.

Declaration long TmGetLastError();

Arguments None

Return value Error number (0: No error)

Note Acquires a description of the error when an error is returned by a library

function.

List of errors

Error no.	Description
1	An invalid argument was specified for the function. Check the argument.
16	Dark measurement has not been performed. Dark correction values cannot be acquired.
17	Reference value correction has not been performed. Reference value correction values cannot be acquired.
32	The sensor unit is not connected. Check the sensor unit connection.
33	The serial numbers of the TM6101 main unit and sensor unit do not match. Check the TM6101 main unit and sensor unit serial numbers.
34	The sensor unit connection cable is connected backwards. Check the direction of the cable connection.
35	The TM6101 main unit or TM6101 with the specified serial number is not connected to the computer. Check the USB and other connections and verify that the driver software has been properly installed.
64	Measurement timed out. Verify that the main unit and sensor unit are properly connected. If performing external trigger measurement, check trigger input.
65	Measurement failed. Verify that the main unit and sensor unit are properly connected.
66	This error is returned by the measurement results acquisition and reference value correction functions if the instrument is unable to calculate color or perform reference value correction.
67	The measurement results are invalid, or measurement has not yet been performed.
68	Sensor detection level overflow. Set the integration time and sensitivity range to appropriate values and repeat measurement.
69	Sensor detection level underflow. The instrument may be malfunctioning.
70	The measurement results exceeded the instrument's rating (100,000 lx). Stop measurement as continuing may damage the instrument.
71	Calculation results are invalid since the Δuv value for the correlated color temperature exceeded 0.02.
72	Unable to start measurement since measurement is currently in progress, or the instrument is not in the measurement standby state.
256	Other error

4.7 Structures

Measurement conditions structure

```
type def\ struct\ tag Tm Meas Set
{
    DWORD dwMeasMode;
                                         //Measurement mode 0: Normal measurement mode
                                                             1: AC measurement mode
     DWORD dwIntTime;
                                         //Integration time
                                         Specify 0 to 10 (corresponds to 0.1 ms to 40 ms)
    DWORD dwAmpSens[16];
                                         //Sensitivity range 0: High
     DWORD
              dwAveNum;
                                         //Averaging times
     DWORD
              dwPlc;
                                         //Power supply frequency
                                                                    0: 60 Hz 1: 50 Hz
     DWORD dwAcRange;
                                         //AC measurement mode measurement range
                                         Specify 0 to 2 (corresponds to ranges 1 through 3)
    DWORD dwAcAveNum;
                                         //AC measurement mode averaging times
     DWORD
              dwExtTrig;
                                         //External trigger 0: Off 1: Rising edge 2: Falling edge
    DWORD
              dwTrigDelay;
                                         //Trigger delay (ms)
                                         //External trigger timeout (ms)
     DWORD
              dwTrigTimeout;
     DWORD dwIndexOutpTime;
                                         //External I/O index output on time (ms)
     DWORD dwAutoRange;
                                         //Auto-ranging
                                                           0: Auto-ranging off
                                         1: Integration time auto-ranging
                                         2: Amp sensitivity auto-ranging (Normal measurement
                                                                                   mode only)
    DWORD dwAutoLevelHigh;
                                         //Auto-ranging detection level upper limit (%)
    DWORD
              dwAutoLevelLow;
                                         //Auto-ranging detection level lower limit (%)
     DWORD
              dwStdIllumSel;
                                         //Reference light 0: CIE daylight
                                         1: Blackbody radiation 2: Automatic selection
     double
               dLightDistance;
                                         //Light measurement distance (m)
} TM_MEAS_SET, *PTM_MEAS_SET;
```

Reference value correction value structure

 $typedef\ struct\ tagTmUserCorrectData$ DWORD dw Chromaticity Correct Enable;//Chromaticity correction enable/disable 0: Disable 1: Enable double dChromaticityGain[16]; //Chromaticity correction values DWORD dwIlluminanceCorrectEnable; //Illuminance correction enable/disable 0: Disable 1: Enable double dIlluminanceGain; //Illuminance correction value DWORD dwLuminousFluxCorrectEnable; //Luminous flux correction enable/disable 0: Disable 1: Enable double dLuminousFluxGain; //Luminous flux correction value DWORD dwLuminousIntensityCorrectEnable; //Luminous intensity correction enable/disable 0: Disable 1: Enable double dLuminousIntensityGain; //Luminous intensity correction value

} TM_USER_CORRECT_DATA, *PTM_USER_CORRECT_DATA;

Measurement results structure

```
typedef struct tagTmMeasResult
     DWORD dwIlluminanceEnable;
                                                     //Illuminance value valid/invalid
                                                     0: Invalid 1: Valid
     double
                dIlluminance;
                                                     //Illuminance value (lx)
     DWORD
                dwLuminousFluxEnable;
                                                     //Luminous flux valid/invalid
                                                     0: Invalid 1: Valid
     double
                dLuminousFlux;
                                                     //Luminous flux value (lm)
     DWORD
                dwLuminousIntensityEnable;
                                                     //Luminous intensity valid/invalid
                                                     0: Invalid 1: Valid
      double
                dLuminousIntensity;
                                                     //Luminous intensity value (cd)
     DWORD
                dwChromaticityEnable;
                                                     //Tristimulus /chromaticity value valid/invalid
                                                     0: Invalid 1: Valid
      double
                dX;
                                                     //Tristimulus value X
      double
                dY;
                                                     //Tristimulus value Y
      double
                dZ;
                                                     //Tristimulus value Z
      double
                                                     //Chromaticity value x
                dChromticity_x;
      double
                dChromticity_y;
                                                     //Chromaticity value y
      double
                                                     //Chromaticity value u
                dChromticity_u;
      double
                                                     //Chromaticity value v
                dChromticity_v;
     DWORD
                dwColorTempEnable;
                                                     //Correlated color temperature
                                                     ∆uv valid/invalid
                                                     0: Invalid 1: Valid
      double
                dTcp;
                                                     //Correlated color temperature (K)
     double
                dDeltaUV;
     DWORD
                dwColorRenderingEnable;
                                                     //Color rendering index valid/invalid
                                                     0: Invalid 1: Valid
     double
                dRi[TEST_COLOR_NUM];
                                                     //Special color rendering index R1 to R15
      double
                                                     //General color rendering index Ra
     DWORD
                dwDominantEnable;
                                                     //Dominant wavelength/excitation purity
                                                     valid/invalid
                                                     0: Invalid 1: Valid
      double
                dDominant;
                                                     //Dominant wavelength (nm)
     double
                dPurity;
                                                     //Excitation purity
} TM_MEAS_RESULT, *PTM_MEAS_RESULT;
```

Note

The structures used by the library are 8-byte aligned. Structure member alignment should be adjusted as needed to accommodate your development environment.

User's License Agreement

Important

Please read the following agreement carefully. This user's license agreement (hereafter referred to as Agreement) is a legal contract between the software user (individual or institution) and HIOKI E. E. CORPORATION (hereafter referred to as HIOKI). The term "software" includes any related electronic documentation and computer software and media, as well as any printed matter (such as the Instruction Manual).

By installing, reproducing, or using the software, you, the Licensee, agree to accept the license terms set forth in this Agreement.

This software is protected by copyright laws, international copyright agreements, as well as non-corporate laws. The software is a licensed product, and is not sold to the user.

1. License

This Agreement grants you, the Licensee, a license to install a single copy of the software on a specified computer system.

2. Explanation of other rights and restrictions

-1. Restrictions on reverse engineering, decompiling, and disassembling:

You may not reverse engineer, decompile, or disassemble the software.

-2. Separation of components:

This software is licensed for use as a single product. You may not separate the components for use on multiple computer systems.

-3. Loaning:

You may not loan or lease the software.

-4. Transfer of software:

You may transfer full rights in accordance with this Agreement. However, if you do so, you may not retain any copy of the software, but must transfer the software in its entirety (all components, media, related documentation such as the Instruction Manual, and this Agreement), and must ensure that the receiver of the software agrees with the terms set forth in this Agreement.

-5. Cancellation:

In the event that the terms and conditions set forth in this Agreement are violated, HIOKI retains the right to cancel this Agreement without compromise of any of its other rights. In this event, you must destroy all copies of the software and its components.

3. Copyright

The title and copyright rights concerning the software's related documentation, such as the Instruction Manual and copies of the software, are the property of HIOKI and other licensors, and are protected by copyright laws and international agreement regulations. Accordingly, you must treat the software as you would any other copyrighted document. However, you are permitted to make copies as indicated in (A) and (B) below provided such copies are not intended for use other than back-up purposes.

- (A) You may make a single copy of the software.
- (B) You may install this software on a single computer.

However, you may not reproduce the documentation supplied with the software, such as the Instruction Manual.

4. Dual media software

You may receive the same software on more than one type of media. However, regardless of the type and size of media provided, you may only use one media type and only on a single computer. You must not use or install the other media on any other computer. Furthermore, except when transferring the software as stipulated above, you may not loan, lease, or transfer the other media to any other user.

5. Warranty

- -1. HIOKI reserves the right to make changes to the software specifications without any prior warning.
- -2. If the software does not operate in accordance with the supplied Instruction Manual, or the software media or Instruction Manual are damaged in any way, you have one year from the date of purchase to apply for either an exchange or repair at HIOKI's discretion.
- -3. In no event will HIOKI be liable for any damages resulting from fire, earthquake, or actions of a third party under the conditions stated in item number 2 above, or for any damage caused as a result of your using the software incorrectly or under unusual circumstances. Further, the warranty is invalid if the following occurs:
 - (A) Damage incurred through transport, moving, droppage, or any other kind of impact after you purchased the software.
 - (B) Damage incurred through any form of alteration, unwarranted servicing, or any other type of mistreatment.
- -4. In the event that the software is exchanged or repaired, the period of warranty expires on the latest occurring date out of the day stated in the original warranty, and exactly 6 months from the day the exchanged/repaired software is returned to you.
- -5. Regardless of the grounds for making a legal claim, HIOKI and its licensors will not be liable for any damage incurred (including, but not limited to: lost profits, suspension of business, loss of data or lost savings) unstated in the warranty terms for the use of this software. This is true even if HIOKI is notified of the possibility of such damages. In any event, HIOKI's liability shall be limited only to replacing defective software with software that is not defective.







All regional contact information

HIOKI E.E. CORPORATION

81 Koizumi, Ueda, Nagano 386-1192 Japan

2309 EN

Edited and published by HIOKI E.E. CORPORATION

Printed in Japan

- Contents subject to change without notice.
 This document contains copyrighted content.
 It is prohibited to copy, reproduce, or modify the content of this document without permission.
 Company names, product names, etc. mentioned in this document are trademarks or registered trademarks of their respective companies.

- Europe only
 •EU declaration of conformity can be downloaded from our website.
 •Contact in Europe: HIOKI EURPOPE GmbH
 Helfmann-Park 2, 65760 Eschborn, Germany

hioki@hioki.eu