# 9008

### **CLAMP ON PROBE**

### **INSTRUCTION MANUAL**

このたびは、日置 "9008クランプオンプロー ブ"をご選定いただき誠にありがとうございま す。この製品を十分にご活用いただき、末長く ご使用いただくためにも、取扱説明書はてい ねいに扱い、いつも手元に置いてご使用くだ さい。

### △ WARNING

This Instrument is designed to prevent accidental shock to the operator when properly used. However, no engineering design can render safe an instrument which is used carelessly. Therefore, this manual must be read carefully and completely before making any measurement. Failure to follow directions can result in a serious or fatal accident.

### 仕 様

測 定 レ ン ジ: AC 10/20/50/100/200/500A

出 力 電 圧:AC0.2V/f.s. (出)抵抗約150Ω:

10Aレンジにおいて)

許 容 差:±3%f.s.

最高使用回路電圧:AC 600Vrms

とケース、ケー奏とコア間)

測定可能導線径:約φ46mm以下

コ - ド 長:約3 m

外形寸法·重 量:約152H×80W×33Dmm·約400g

### 使用上の一般的注意

- 1. 測定に際しては、過大入力のないよう十分注意 して下さい。
- 2. 感電事故のないよう十分注意して下さい。裸電線をクランプすることはなるべく避けて下さいまた、回路電圧が600V以上の高圧での使用はしないで下さい。
- トランスや大電流電線など、強磁界の発生している近くでの測定はなるべく避けて下さい。
- 4. 保管に際しては高温・多湿および結露させるような場所は避けて下さい。特に直射日光下、および熱的衝撃の加わるような場所に保管しないで下さい。

### 使用方法

- ●当社8202マイクロハイコ ータへ入力する場合は、 AC 0.2Vレンジをご使用 下さい。
- 電流記録計として下記セットでご購入された場合の、組み合わせ許容差は ±3%f.s.です。

### 雷流記録計

8202-20: AC電源、8202+9008 + 9086(ケース)付 8202-21: AC・DC両用電源、 8202+9008+9086


(ケース)付



- 1. 測定電流の大きさがわからない時は、大きいレンジ(500A)にセットして下さい。
- 2. クランプコアを開き導体をクランプして下さい。
  - 単体は一本だけクランプして下さい。
  - ■コア先端接合部が確実に閉じていることを確認 して下さい。
- 測定値に合わせて、クランフオンフローアのレンジを切換え、適切なレンジで測定して下さい。
  - 測定器(記録計)側のレンジ切換えにての測定 はしないで下さい。

### 二芯コード付電気器具の 電流を測定する場合

コンセント類より使用する二志コード付き電気器具 の使用電流を測定する場合は、別売のCT-101A ライ ンスプリッターをご使用下さい。



計画の生進機能を社会に

## HIOKI

### 日置電視株式会柱

 北関東(宮) 田048-266-8161 駅(048-269-3842 〒333 パロ市芝中田2-23-24 神奈川宮) 田0462-24-8211 駅(048-24-8921 〒312 東京日村町8-5

1

広島(客) 位(82-242-1250 M)062-242 1250 〒730 広島市中区大手町4-6-16 福岡(営) 配 092-482-3271 限 092-482-3275 〒812 福岡市博多区博多駅東 3-10-15

※お問い合わせは最寄の営業所または本社営業企画部まで。

### SPECIFICATIONS

Measuring ranges: 10/20/50/100/200/500A AC

Output voltage: 0.2VAC f.s. (Output resistance, approx

 $150\Omega$  in the 10A range)

Accuracy: ±3%fs.

Max. voltage for use: 600V rms AC

Dielectric strength: 1500V rms AC for one minute (electrical

circuit and case, and case, and core)

DIA. of clamp part: up to \$46mm

Cord length: Approx. 3m

Dimensions, Weight: Approx 152H×80W×33D mm.

Approx 400g

### CAUTIONS CONCERNING USE

- Take care to avoid excessive input
- To avoid electric shock, as a rule do not clamp bare wires or test equipment where the circuit voltage is 600V or over.
- Try to avoid taking measurements close to transformers or power lines carrying high amperages where strong magnetic fields are produced.
- When storing, avoid hot, humid places and places where dew will form on the tester. Take particular care to avoid direct sunlight or places where heat shock will occur when selecting a place to store the tester.

### HOW TO USE THE PROBE

- When connecting to the input of the HIOKI 8202 Micro Hi Corder, use the 0.2V AC range on the 8202.
- When purchased as a current recorder, combined accuracy is - 3% fs.



### CURRENT RECORDER


8202-20: AC power supply, with 8202 + 9008 + 9086 (case) 8202-21: AC-DC power supply,

8202 + 9008 + 9086 (case)

- When the user has no idea at all of the amount of current to be measured, use the high (500A) range.
- 2. Open the clamping core and clamp over the conductor.
  - \* Clamp only one conductor at a time.
  - \* Make sure that the ends of the clamp close properly.
  - Select the correct clamp on probe range to suit the value measured.
    - \* Do not use the measuring instrument (recorder) side range selector in measuring.

# When measuring the current in electrical appliances with two-wire cords:

When measuring the current used by two-wire electrical appliances which connect plug sockets, use the CT-101A Line Splitter (special accessory, not included in the price of the probe).



### HIOKI E.E. CORPORATION

81 Koizumi, Ueda, Nagano 386-11, Japan TEL 0268-28-0562 FAX 0268-28-0568 TLX:3327508 HIOKI J CABLE:HEWLOV, Ueda

ラベルなどの日本かれる CARL TOTAL PA

册

野

벌

账

+

無償後期いたし

にしたがった上密な他用状態で,

**成极展明智、本体制意** に放降した場合には、

次の場合には有償修理

(Sar Dilitivice).

---

# 

当日の最高ある検査を持てお届けしたもので

こ使用では保険が発生した場合は、お買い水の光してください。本書記載内容で無償が呼らませています。 保利の際は、本書を提示してください。 CERTAL CA

· 公报, 照常在日本上が風貌, 出。風

の場合。

200

(所作の中 その他人気温楽など

14 AU 1:07 SUTE

2 04 III PG C

各 BK BA 13 13 CV 111 (14)。 10.00

N. Y

24.各場合。

された場合など

日間いこけ後の情景を認

る松原はままが相偽。

4

または他用しの誤りによる故障および相似 不当な修正や収過による故障および制傷。 **収機説明書に基づかない不適当な収扱い** 

を祈り指示がない場合。

を出り

=

その便当れの責任とみなされない機能 his warranty is valid only in Japan. 本保証 芸は日本国内のみ有効です × E C K П I # \*

> 剛紫世 HEE TH 書の再発行はいたしませんので、大切に保 影響 1 〒386-11 12JPR LIII-14-5281 TEL 0268 (28) 0555 (ACA) 國語就採以即